

# LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: See below

For corner(s) in: Iron County

## Original Public Land Survey Corner

## Corner Code

S          T          R           
S          T          R           
S          T          R           
S          T          R         

## Property Corner

## 1/16 Corner Code

a. S 1 T 44N R 32W 15 (GCDB 620600)  
a. S 12 T 44N R 32W 1 (GCDB 620600)  
b. S 11 T 44N R 32W 7 (GCDB 600560)  
b. S 12 T 44N R 32W 3 (GCDB 600560)

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

## Part A: Corner History

a. West 1/16 corner between Sections 1 and 12 T44N-R32W. 1989 - Recorded by K.L.Sackett RLS. Found and accepted a 1 1/2" diameter iron pipe. 14" Y.Birch N32°W 9.0'; 9" Maple S60°W 13.0'; 9" Maple S74°E 7.7'.

b. North 1/16 corner between Sections 11 and 12. 1989 - Recorded by K.L.Sackett RLS Found and accepted a 1 1/2" diameter iron pipe. 15" Cedar S40°E 21.7'; 5" Balsam N18°W 35.0'; 6" Balsam S40°W 35.8'. The 1989 record states that the pipe was found 5.8' east of midway on line.

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a. May 21 2018. Found a 1.5" ID iron pipe, in good condition, standing about 3 ft. a.g., at record bearing and distance from the 1989 witnesses. The two Maple BTs are green and standing with overgrown blazes. The Y.Birch BT is a dead stub. Accepted the monument as a careful and faithful establishment of the position of the corner.

b. May 21 2018. Found a 1.5" ID iron pipe in good condition, standing about 3 ft. a.g., 5.8' east of a straight line between Section and Quarter corners, at record bearing and distance from the dead and down remains of the Balsam BT S40°W. The Balsam BT N18°W was not evident. An unmarked Cedar was found at near record bearing and distance to the record BT Cedar S40°E but is not obviously the 1989 BT. I accepted the pipe as a careful and faithful determination of the position of the corner.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

a. Found 1.5" dia. iron pipe 3 ft. above ground.  
Set measuring nail with MDNR tag in the side of:  
12" Maple S78°E 8.2' overgrown blazes (1989 BT)  
10" Maple S60°W 12.55' do do  
5" Balsam N52°E 15.45' mrkd "1/16S BT"  
18" Maple N05°W 23.2' do  
Set sq'd spruce post adjacent.  
E= 7902975.49 N= 161807.13

b. Found 1.5" dia. iron pipe 3 ft. above grnd.  
Set measuring nail with MDNR tag in the side of:  
11" W.Birch N35°E 10.0' mrkd "1/16S BT"  
15" Cedar S45°E 22.4' do  
6" Maple S27°E 17.4' do  
2" Maple N48°W 9.25' mrkd "X X"  
Set sq'd spruce post adjacent.  
E= 7902564.10 N= 161411.72

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00

Stephan J. Szyszkoski

05/30/2018

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

