

SURVEY & REMONUMENTATION

JAN 13 1998

SECTION

IRON COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

97 DEC 23 PM 1:26

L.C. Records L. 7 P. 125

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

REGISTER OF DEEDS

For corners in

Iron  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 44N R 32W

E-9

2. Property Controlling  
in Section

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

Section Corner Sec. 20, 21, 28, 29, T44N, R32W

I, Gary L. Pisoni, in a field survey on November 5, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

Register of Deeds Stamp & File Number

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in July of 1849 by Zelotes B. Searls, U.S. Deputy Surveyor.

Original Corner; Hemlock Post

Original Bearing Trees;

Cedar	10"	S81° W	30 links (19.80 feet)
Sugar	14"	N50° E	35 links (23.10 feet)

On 8-17-84, Keith L. Sackett, RLS with the Michigan Dept. Of Natural Resources, found a Michigan Wisconsin Power Company monument and restored same. Recorded in Land Corner Certificate L. 5, Page 81, on September 14th, 1984.

1984 Bearing Trees;

Maple	4"	N60°E	8.1 feet
Maple	6"	S47°E	17.5 feet
Balsam	7"	S21°W	10.4 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 11-5-97, found monument as described above and the following bearing trees;

Sugar Maple	10"	S44°E	17.71 feet
Balsam	11"	S26°W	10.60 feet

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (all measurements taken to a nail in side of tree)

Sugar Maple	5"	N18°E	30.11 feet
Sugar Maple	5"	S81°W	22.91 feet
Steel Sign Post		N67°E	1.10 feet

PEER GROUP APPROVED

Gary L. Pisoni 11-11-97  
IRON COUNTY REGISTERED LAND SURVEYOR

97-20

Signed by Gary L. Pisoni

Date November 7, 1997

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995