

**SURVEY & REMONUMENTATION**

**FEB 21 2001**

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
 Filing Requirement of Act 74, Mich. P.A. 1970

or corners in

<u>Iron</u> (County)	Located In:	Corner Code #
Public Land Survey	T <u>44N</u> R <u>R33W</u>	<u>K-4</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
1. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
2. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

COMMENCING YEAR 2000  
 RECEIVED FOR RECORD  
 IRON COUNTY, MICHIGAN

DO DEC 22 PM 3:24

*L.C. Records: L.S.P. 300*  
*[Signature]*  
 REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

1. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 2. Private Claims \_\_\_\_\_  
 Quarter Corner Between Sections 11 and 12, T44N, R33W

Gary L. Pisoni, in a field survey on November 8, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on June 15, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.  
 Original Corner; Wood Post  
 Original Bearing Trees:  
 Sugar 8" N 85° E 14 links (9.24 feet)  
 Cedar 14" S 50° W 12 links (7.92 feet)

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Corner located in a popple clear cut.

Restored the corner position by single proportionate measurement and on line between the Northwest and Southwest Section corners of Section 12.

Corner record research on file with County Representative.


PEER GROUP APPROVED

*[Signature]* 12-20-2000  
 COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T44N, R33W, 1/4, S-11, S-12, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Popple	5"	N 58° E	27.33 feet
Black Spruce	8"	S 39° E	39.76 feet
Balsam	4"	S 80° W	11.34 feet
Black Spruce	3"	N 38° W	8.68 feet
Steel sign post		South	0.7 feet



00-068  
 Signed by Gary L. Pisoni Date 12-19-2000  
 Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN., 1983  
 REVISED OCT., 1995