

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 44N R 33W

L-3

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S     

T      R     

S     

T      R     

3. Miscellaneous  
Property in Sec.

S     

T      R     

S     

T      R     

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC 22 PM 3:24

*L.C. Records: L-3, P. 299*

*Gary L. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No.         , Recorded Plat         

5. Private Claims         

Quarter Corner Between Sections 1 and 12, T44N, R33W

I, Gary L. Pisoni, in a field survey on December 4, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on June 15, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.

Original Corner: Wood Post

Original Bearing Trees:

Fir	10"	S 46° E	11 links (7.26 feet)
Tamarack	12"	N 35° W	32 links (21.12 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Corner located in a flooded beaver flowage area.

Restored the corner position by single proportionate measurement and on line between the Northwest and Northeast Section corners of Section 12.

Corner record research on file with County Representative.

PEER GROUP APPROVED  
*Iron County 12-20-2000*  
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 3/4" outside diameter aluminum rod monument, 7 feet long, 3" above water surface with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T44N, R33W, 1/4, S-1, S-12, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Tamarack	13" (dbl)	N 44° W	77.42 feet
Black Spruce	11"	N 03° W	48.97 feet
Tamarack	4"	N 84° E	37.35 feet
Tamarack	10"	S 62° E	52.73 feet
Steel sign post		N 60° W	1.3 feet

00-067

Signed by *Gary L. Pisoni*

Date 12-19-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995

