

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 7 T 44N R 34W S _____ T _____ R _____ S 7 T 44N R 34W	B4 (GCDB 140540) 10 (GCDB 100520)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4													
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 06/17/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B4) Center of Section 7. Not previously monumented.

(10) South 1/16 corner common to Section 7 T44N-R34W and Section 12 T44N-R35W. Not previously
monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B4) Established the position for the corner at the intersection of straight lines connecting
opposite 1/4 corners.

(10) Established the position for the corner midway and on the Range line between Section corner
1317.81' south and Quarter corner 1317.81' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B4) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
2" Tamarack S46°E 7.25' mrkd "X X"
2" Tamarack S02°E 18.2' do
2" Tamarack N42°W 24.8' do
3" Cherry S63°W 9.0' mrkd "C1/4 BT"
Set sq'd Cedar post adjacent.
E= 7876077.402 N= 161441.455

(10) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Maple N24°E 9.2' mrkd "1/16S BT"
10" Sugar N75°E 4.1' do
7" Sugar S74°W 5.9' do
5" Sugar N13°W 25.1' do
Set sq'd Spruce post adjacent.
E= 7875277.724 N= 161072.525

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID DI0209: N= 145460.522 m. E= 7873677.972 m.

Signed by Stephan J. Szyszkoski Date 06/23/2014
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division