

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located In:

Corner Code #

1. Public Land Survey

T 44N R 34W

A-4 ✓

T 44N R 35W

M-4

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 12: 59

L.C. Records: L. 8, P. 235

Gary L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Quarter Corner to Section 12, T44N, R35W

Quarter Corner to Section 7, T44N, R34W

I, Gary L. Pisoni, in a field survey on March 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 15, 1846 by William A. Burt, U.S. Deputy Survey

Original Corner; Cedar Post

Original Bearing Trees:

White Pine 16" S 83° E 26 links (17.16 feet)

Cedar 16" N 32° W 19 links (12.54 feet)

On 10/1/75, Arthur O. Enger, RLS DNR restored the quarter corner position from the remains of a rotted white pine bearing tree stump as described above, set a 1" diameter by 36" iron pipe with a 3 1/2" diameter aluminum capped stamped as follows: T44N, R35W, R34W, 1/4, S-12, S-7, 10/1/75, RLS 13581. Recorded in Liber 1, Page 511 of LC Records.

1975 Bearing Trees:

Red Maple 10" S 72° W 7.2 feet

Sugar Maple 6" S 75° E 8.5 feet

PEER GROUP APPROVED

Gary L. Pisoni 11-30-2000

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found remains of white pine bearing tree and on 3/18/2000 found monument as described above and the following described bearing trees:

Red Maple 13" S 76° W 7.28 feet

Sugar Maple 10" S 73° E 8.66 feet

Found existing bearing trees and steel rail which was established by the U.S.F.S as described below:

Red Maple 11" N 28° E 18.62 feet

Red Maple 11" N 35° W 20.11 feet

Steel sign post S 44° E 0.4 feet

Monument is 10" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

00-003
Signed by Gary L. Pisoni

Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995