

SURVEY &  
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Iron (County)	Located In:	Corner Code #
1. Public Land Survey		T. 44N R. 34W T. 44N R. 35W T. R. T. R.	A-4 M-4 ✓  
2. Property Controlling in Section	S. T. R. S. T. R.		
3. Miscellaneous Property in Sec.	S. T. R. S. T. R.		

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8, PM 12: 59

L.C. Records: L. S. P. 235

*Gary L. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Quarter Corner to Section 12, T44N, R35W  
Quarter Corner to Section 7, T44N, R34W

I, Gary L. Pisoni, in a field survey on March 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 15, 1846 by William A. Burt, U.S. Deputy Survey  
Original Corner; Cedar Post

Original Bearing Trees:

White Pine	16"	S 83° E	26 links (17.16 feet)
Cedar	16"	N 32° W	19 links (12.54 feet)

On 10/1/75, Arthur O. Enger, RLS DNR restored the quarter corner position from the remains of a rotted white pine bearing tree stump as described above, set a 1" diameter by 36" iron pipe with a 3 1/2" diameter aluminum capped stamped as follows: T44N, R35W, R34W, 1/4, S-12, S-7, 10/1/75, RLS 13581. Recorded in Liber 1, Page 511 of LC Records.

1975 Bearing Trees:

Red Maple	10"	S 72° W	7.2 feet
Sugar Maple	6"	S 75° E	8.5 feet

PEER GROUP APPROVED

*Gary L. Pisoni* 11-30-2000  
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found remains of white pine bearing tree and on 3/18/2000 found monument as described above and the following described bearing trees:

Red Maple	13"	S 76° W	7.28 feet
Sugar Maple	10"	S 73° E	8.66 feet

Found existing bearing trees and steel rail which was established by the U.S.F.S as described below:

Red Maple	11"	N 28° E	18.62 feet
Red Maple	11"	N 35° W	20.11 feet
Steel sign post		S 44° E	0.4 feet

Monument is 10" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

00-003

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995