

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970 as Amended**

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 29 T 45N R 31W	4
	S _____ T _____ R _____	(GCDB 220260)
	S 29 T 45N R 31W	8
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	(GCDB 220240)
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		10		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/23/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(4-Sec. 29) Northwest 1/16 corner, Section 29. Not previously monumented.

(8-Sec. 29) Center-West 1/16 corner, Section 29. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(4-Sec. 29) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

(8-Sec. 29) Established the position for the corner midway and on a straight line between Quarter corner C10 1316.59' west and the intersection of 1/4 lines of Section 29 1316.59' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
 Set measuring nail with MDNR tag in the side of:  
 5" Poplar N15°E 9.95' mrkd "1/16S BT"  
 4" Cherry S34°E 1.15' do  
 4" Balsam S87°W 18.9' do  
 4" Poplar N46°W 3.4' do  
 Set sq'd cedar post adjacent.  
 E= 7906252.985 N= 166148.815

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
 Set measuring nail with MDNR tag in the side of:  
 9" twin Sugar S28°E 6.8' mrkd "1/16S BT"  
 4" Sugar S18°W 10.1' do  
 8" Sugar N03°W 22.4' do  
 5" Sugar N33°E 22.5' do  
 Set sq'd cedar post adjacent.  
 E= 7906247.165 N= 165747.951

**Bearings are magnetic.** Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
 Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski Date 08/04/2015  
 Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division