

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron Located In: Corner Code #
1. Public Land Survey T 45N R 31W E10
2. Property Controlling in Section S 29 T 45N R 31W 9
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 06/22/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E10) Quarter corner common to Sections 28 and 29. 1849 - Established by John Burt, Deputy Surveyor, midway and on the Section line between Section corners 40.00 chains north and south. Set post. Y.Birch 7" S20°E 49 links, Sugar 14" N79°W 55 links.

(9-Sec. 29) Center-East 1/16 corner, Section 29. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E10) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2621.10' north and south.

(9-Sec. 29) Established the position for the corner midway and on a straight line between Quarter corner E10 1316.59' east and the intersection of 1/4 lines of Section 29 1316.59' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E10) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Balsam N15°E 10.25' mrkd "1/4S NBT" 3" Balsam S70°E 12.6' do 9" Poplar S21°E 6.7' do 6" Poplar N85°W 14.9' do Set sq'd cedar post adjacent. E= 7907450.615 N= 165723.804

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. The corner falls on the lower face of a hill on the north edge of a burned over swamp. No witnesses are available. Set sq'd cedar post North 0.9' from the corner monument. E= 7907049.465 N= 165731.853

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by [Signature] Surveyor's Michigan License No. 33986

Date 08/04/2015

For the Michigan Department of Natural Resources, Forest Resources Division

