

# LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: 05/19/2016 & 8/31/16

For corner(s) in: Iron County

<b>Original Public Land Survey Corner</b>		<b>Corner Code</b>
a. S	T 45N R 31W	G09 (GCDB 400300)
S	T	
S	T	
S	T	
<b>Property Corner</b>		<b>Corner Code</b>
b. S 22	T 45N R 31W	15 (GCDB 420300)
b. S 27	T 45N R 31W	1 (GCDB 420300)
S	T	
S	T	

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9							●	●						9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

## Part A. Corner History

a.) Corner common to Sections 21-22-27-28. 1849 - Established by John Burt, Deputy Surveyor. Set post. Y.Birch 22" S75°W 22 links, Cedar 6" N44°E 23 links. 2010 - Reestablished by David E. Erickson, PS by double proportionate measurement to the original GLO record. Set 5/8"x28" rebar with 2" aluminum cap PS #29245 from which a nail and DEE tag was set in: N. face 4" Maple N63°E 36.85'; N. face 16" Spruce N82°E 74.84'; NE face 12" Maple N25°W 32.49'; NE face 10" Maple N56°W 51.89'; SE face 16" Spruce S46°W 11.84'. The record given here is from the 2010 field notes of Mr. Erickson.

b.) West 1/16 corner between Sections 22 and 27. Not previously monumented.

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) The original post and accessories were not recovered. Found the 2010 monument in good condition and at record bearing and distance from the 2010 witnesses. Found the monument to be substantially in accord with the prorated original record distances to corners 5270.90' East, 5256.66' South, 5269.49' West, and 7874.28' North. I accept the monument as a careful and faithful reestablishment of the position of the original corner.

b.) Established the position for the corner midway and on the Section line between Section corner 1317.72' west and Quarter corner 1317.72' east. Corner monumented Aug. 31, 2016

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Found 5/8" rebar with aluminum cap PS #29245. Found measuring nail with tag in the side of:  
 4" Maple N63°E 36.85'  
 16" Spruce N82°E 74.84'  
 12" Maple N25°W 32.49'  
 10" Maple N56°W 51.89'  
 16" Spruce S46°W 11.84'  
 E= 7909063.911 N= 166510.956

b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
 8" Tamarack S53°W 8.4' mrkd "1/16S BT"  
 8" Tamarack N48°W 10.7' do  
 5" Tamarack N47°E 14.65' do  
 7" Tamarack S49°E 15.3' do  
 Set sq'd cedar post adjacent.  
 E= 7909465.3777 N= 166501.6258

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters. Coordinate Reference: NGS PID RL0202, E= 7917031.357 m. N= 156159.387 m.

Stephan J. Szyszkoski 08/31/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

