

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: August 30, 2016

For corner(s) in: Iron County

Original Public Land Survey Corner		Corner Code
a. S _____	T 46N R 32W	G08 (GCDB 400340)
b. S _____	T 46N R 32W	J07 (GCDB 540400)
S _____	T _____ R _____	_____
S _____	T _____ R _____	_____
Property Corner		1/16 Corner Code
S _____	T _____ R _____	_____
S _____	T _____ R _____	_____
S _____	T _____ R _____	_____
S _____	T _____ R _____	_____

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7										●				7
8		19		20		21	●	22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

- a.) Quarter corner common to Sections 21 and 22. 1852 - Established by Francis Houck, U.S. Deputy. Set post midway and on the Section line between Section corners 39.885 ch. North and South. Fir 8" N65°E 12 links, Sugar 8" S63°W 24 links. Found no subsequent record.
- b.) Quarter corner common to Sections 14 and 23. 1852 - Established by Francis Houck, U.S. Deputy. Set post midway and on the Section line between Section corners 40.00 ch. east and west. Maple 10" N40°E 10 links, Sugar 12" S27°W 24 links. Northern Paper Mills records: 1931 - Buell and Ellison found both B.T.s. Set post. 1954 - Wickman and Peryam found post - 16" Sugar S27°W 24 links rotted out face. Red Maple N40°E 10 links down rotting. Iron marks faint. Set pipe with brass cap from B.T.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

- a.) The original post and accessories were not recovered. At a position consistent with the original record, I found a old 1-1/4" ID iron pipe. Did not observe any existing witness trees. I accepted the position of the pipe as the best available evidence of the position of the original corner.
- b.) Found the 1954 monument in good condition and at record bearing and distance from the 1954 witnesses, now both rotted stumps. Accepted the position of the monument as a careful and faithful perpetuation of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

- | | |
|---|---|
| a.) Found 1-1/4" ID iron pipe.
Set measuring nail with MDNR tag in the side of:
11" W.Spruce N33°E 7.4' mrkd "1/4S NBT"
11" Maple S32°E 12.85' do
6" Balsam S28°W 7.7' do
6" twin Y.Birch S54°W 30.8' do
Set sq'd cedar post adjacent.
E= 7899615.048 N= 177112.069 | b.) Found 1" ID I.pipe with 2" brass NPM cap.
Set measuring nail with MDNR tag in the side of:
9" Maple N58°E 7.4' mrkd "1/4S NBT"
7" Sugar S49°E 15.65' do
7" Sugar S60°W 9.65' do
11" Y.Birch N04°W 23.0' do
Set sq'd cedar post adjacent.
E= 7902049.666 N= 177875.975 |
|---|---|

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters
Coordinate Reference: MDNR Network control "BONE", a 1" ID I.pipe
with 2" alum cap., E= 7899059.778 m. N= 176329.657 m.

Stephan J. Szyszkoski 10/13/2016

