

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 29 T 46N R 33W S _____ T _____ R _____ S 32 T 46N R 33W	16 (GCDB 260200) 6
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 260160) _____
4. Lot No. _____, Recorded Plat	_____	_____
5. Private Claims	_____	_____

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		6		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 06/02/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 29) East 1/16 corner between Sections 29 and 32. Not previously monumented.

(6-Sec. 32) Northeast 1/16 corner, Section 32. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 29) Established the position for the corner midway and on the Section line between Section
corner 1313.27' east and Quarter corner 1313.27' west. From the position established I found a 3/4"
ID I.pipe, projecting 3 ft. above ground, a land-owner's approximate position, N54E 4.4' distant,
not accepted as marking the position for the corner.

(6-Sec. 32) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Sugar N74°E 16.55' mrkd "1/16S BT"
15" Sugar S68°E 32.3' do
14" Sugar S47°W 32.3' do
12" Sugar N58°W 15.6' do
Set sq'd cedar post adjacent.
E= 7888005.265 N= 174915.945

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
13" Spruce N50°E 16.05' mrkd "1/16S BT"
3" Cherry S69°E 13.35' do
8" twin Maple S35°W 17.85' do
9" Maple in clump N79°W 13.75' do
Set sq'd cedar post adjacent.
E= 7887996.652 N= 174513.112

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski Date 08/06/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division