LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in				
Iron	Located In:	Corner Code #		98
(County)				10
1. Public Land Survey	TR			
2. Property Controlling in Section	S 18 T 46N R 34W S T R	11		
3. Miscellaneous	S 18 T 46N R 34W S T R	(GCDB 120420) 10 (GCDB 100420)		
Property in Sec.	STR		Register of Deeds Stamp & F	File Number
4. Lot No. , Re 5. Private Claims	corded Plat		A B C D E F G H	I J K L
		:	2 - 6 - 5 - 4 - 3	
ı, Stephan J. Szyszkoski , i	in a field survey on 10/2	28/14 do hereby state	· 	
that under requirements of P.A.	74, Michigan P.A. of 1970, the corner po	pints mentioned in lines 1 and 2	┖ ┋	11-12
above were in conformance with	regulations and rules therefore as required	in the current manual of survey	ĭ ┞╶┩┈╎╸ ╏┈╎╸ ┩	
instructions of the United States	Department of the Interior, Bureau of Lan	d Management or by a decree of	19-17-16-15	1413-
the rules of the Michigan Roar	corner points mentioned in lines 3, 4 and 5 rd of Land Surveyors or by a Decree of	above were in conformance with	'T 	++++
re-established, monumented, recov	vered. found as expressed below:	or a Court of Law; established, a	3 - 19 - 20 - 21 - 22	23 24-
,	and the state of t	\$	° ├─┼─┼─┼ ─┼ ─	
NOTE: Not more than 2 core	ners, all in the same town and range,	may be recorded	0 29 29 27	26-25-
on this certificate.	, an in the same town and range,	1 1	1	- 40
		1	2 -31 - 32 - 34	36-
A Doscription of arisinal		. 1	3	
A. Description of original if	nonument and accessories and/or su	Disequent restoration:	* STEPHA	N J.
			* SZYSZKI	
(11-Sec. 18) Southwes	st 1/16 corner, Section 18.	Not previously monum	ented. SURVEY	
		, p====================================	No.	13
			3398	6
			AND	SUR
/10 0 10) 0 ()				Marian.
(10-Sec. 18) South 1/ previously monumented	/16 corner between Section	18 T46N-R34w and Secti	on 13 T46N-R35W. Not	
brostoggt woundlended	۸.			
B. Description of corner ev	idence found and/or method applie	ed in restoring or reestablishing	ng corner:	23
	•••	3	is contain	
(11-Sec. 18) Establis connecting opposite 1	shed the position for the c 1/16 corners.	orner at the intersect	ion of straight lines	
480.0				
corner 1318.57' south	shed the position for the c n and Quarter corner 1318.5	orner midway and on th 7' north.	e Range line between	Section
C. Description of monumen	nt for corner and accessories establi	shed to perpetuate locating	the position of the corner:	
(11) Set 1"TDv28" T v	pipe with 2" alum. MDNR cap	/101 0-2 4		
Set measuring nail wi	ith MDNR tag in the side of		" I.pipe with 2" alum.	MDNR cap.
4" B.Spruce S06°W 31.	.7' mrkd "1/16S BT"	10" Spruce N27°	ail with MDNR tag in t	he side of: "1/16S BT"
2" Balsam N47°W 27.6	do	9" Y.Birch N68°	E 15.1'	do BI
8" Cedar N03°E 43.8' 18" Cedar N62°E 24.65	do	11" Cedar S47°E	4.5'	do
Set sq'd cedar post a		4" Balsam S64°W		do
E = 7876014.766 $N = 17$	78746.378	Set sq'd cedar p E= 7875638.162	post adjacent. N= 178751.917	
		977		
Desings	makin a second			
bearings are mag	netic. Coordinates are MCS8	3 in meters, NAD83(201	1) Epoch 2010.00 datur	m.
Coord.	Ref.=NGS PID RL0476: N= 1	96482.411 m. E= 787923	34.516 m.	
Signed by	1 1.1 - 0.1			
Virapie	- Jynyaya	Date 0	05/19/2015	
Surveyor's Michigan License No	33986			