

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 22 T 46N R 34W	7 (GCDB 500360)
	S 28 T 46N R 34W	3 (GCDB 300260)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 7 01/21/15
3 02/12/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(7-Sec. 22) North 1/16 corner between Sections 22 and 23. Not previously monumented.

(3-Sec. 28) North 1/16 corner between Sections 28 and 29. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(7-Sec. 22) Established the position for the corner at GLO record distance 20.06 chains (1323.96')
north of I8 (but proportioned to the observed distance between I8 and I9, yielding a measured
distance of 1322.14' north of I8) and on the Section line I9 through I8, produced northerly.

(3-Sec. 28) Established the position for the corner midway and on the Section line between Section
corner 1321.28' north and Quarter corner 1321.28' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
14" Cedar S28°E 14.9' mrkd "1/16S BT"
5" Tamarack S70°W 15.25' do
5" Tamarack N61°W 6.15' do
6" Tamarack N32°E 10.65' do
Set sq'd cedar post adjacent.
E= 7882035.015 N= 177856.566

(3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" Cedar N14°W 36.7' mrkd "1/16S BT"
6" Cedar N85°E 20.7' do
7" Cedar S09°W 17.3' do
10" Cedar N71°W 23.45' do
Set sq'd cedar post adjacent. Note: All the
marked BTs are standing dead timber.
E= 7878792.544 N= 176292.841

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/19/2015

For the Michigan Department of Natural Resources, Forest Resources Division

