

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 28 T 46N R 34W	1
	S T R	(GCDB 320300)
	S 33 T 46N R 34W	9
	S T R	(GCDB 360140)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

102

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 1 02/12/15
9 05/04/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 28) West 1/16 corner between Sections 21 and 28. Not previously monumented.

(9-Sec. 33) Center-East 1/16 corner, Section 33. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 28) Established the position for the corner midway and on the Section line between Section
corner 1319.11' west and Quarter corner 1319.11' east.

(9-Sec. 33) Established the position for the corner midway and on a straight line between Quarter
corner 1320.04' east and Center of Section 33 1320.04' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Maple N41°W 10.65' mrkd "1/16S BT"
6" Y.Birch N50°E 6.0' do
6" Maple S74°E 13.1' do
8" Y.Birch S21°E 21.85' do
Set sq'd cedar post adjacent.
E= 7879201.453 N= 176687.168

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Y.Birch N34°W 22.75' mrkd "1/16S BT"
16" Hemlock N42°E 3.4' do
12" Hemlock S08°W 13.3' do
14" Hemlock N67°W 10.9' do
Set sq'd cedar post adjacent.
E= 7879955.385 N= 174259.411



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/19/2015

For the Michigan Department of Natural Resources, Forest Resources Division