PE JOSEPH TO

LAND CORNER RECORDATION CERTIFICATE

	nt of Act 74, Mich. P.A. 19	70 MAR () 1 2000
For corners in	1	in one of the state of the
KALKASKA Located In:	Corner Code #	SECTION
1999 REMONUMENTATION 1. Public Land Survey TR TR TR	B-7	7000440
2. Property Controlling STR	Kalƙaska County J	Page: 1 of 1 92/04/2000 03:40F REMON Can Hall, Register LB: 6 PG: 95 Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		
		ABCDEFGHIJKL
5. Private Claims		2 6 5 4 3 2 1 3
		3 4 7 8 9 10 11 12-12-
		5
I, <u>FUGENE FARRIER</u> , in a field survey on <u>November 17</u> under requirements of P.A. 74, Michigan P.A. of 1970, the corner poin		6 -19 -17 -16 -15 -14 -13-
above were in conformance with regulations and rules therefore as req	7	
by a decree of a Court of Law and /or that the corner points mention	ned in lines 3, 4 and 5 above	8 19 20 21 22 23 24
were in conformance with the rules of the Michigan Board of Land S Court of Law; established, re-established, monumented, recovered, fou		10 33 29 28 27 26 25
NOTE: Not more than 2 corners, all in the same town and range, ma	ry be recorded	11
on this certificate.		12 -31 - 32 - 33 - 34 - 35 - 36-
A. Description of original monument and accessories and/or st B-7: 1/4 Cor. Common to Sec. 18 & 19. T25N-R7W, Garfield T 1853, G.L.O. Resurvey, by V.W. Caukin (Deputy Surveyor) Co. Survey Elm 10*, N20°W, 17 Lks; W. Pine 36", S18.25°W, 14 Lks 1972, Survey & LCRC, by J.L. Wilcox, (LCRC recorded in Liber 1, Pg 8 N70°W, 20" Maple, 63.63'; N05°W, SW corner garage footing, 35.4' 1997, Survey, by Farrier Surveying, found 1/2" iron in centerline of Bir N07°W, SW corner garage (conc. foundation) 35.32'; N20°E, SE corn	Township Notes, set 1/4 Section post, set 1/2" iron by proportionate N10°E, SE corner garage foot gy Road; set nail \$10°W, 4" R.	ling, 37.2' . Pine, 74.87'; set nail S55°W, fence post, 56.53';
B. Description of corner evidence found and/or method applied in rest B-7: 1/4 Cor. Common to Sec. 18 & 19. T25N-R7W. Garfield 7 Found 1/2" rered in centerline E-W road. N20°E, 137.15', SE corner garage \$10°W, 74.87', 4" R. Pine, found nail \$55°W, 56.53', fence post, found nail N07°W, 135.32', SW corner garage No G.L.O. witnesses were found.	toring or reestablishing corner:	EUGENE D. FARRIER PROFESSIONAL SURVEYOR NO. 24594
C. Description of monument for corner and accessories established to B-7: 1/4 Cor. Common to Sec. 18 & 19. T25N-R7W. Garfield Tound 1/2" rerod in centerline E-W road. Pulled & set 5/8" X 18" rerod N20°E, 137.15', SE corner garage \$10°W, 74.87', 4" R. Pine, found nail \$55°W, 56.53', fence post, found nail N07°W, 135.32', SW corner garage Kalkaska County Peer Group accepted the above monument as a caref	<u>Fownship</u> d w/brass cap in mon box.	