

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Kalkaska
(County)

Located In

Corner Code #

1. Public Land Survey	T	26N	R	5W	H5
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Joshua R. Davidson, in a field survey on June 24, 2014 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

H5 – ¼ corner common to sections 10 & 15, T26N, R5W

- 1852 – GLO Resurvey – G. Cannon – Set quarter section post. – 1) Cedar 4" N20°W 10, 2) Cedar 6" S10°E 17.
- 1913 – Fargo Engineering – Found very old stake and both U.S. witnesses. – 3) Tamarack 6" N4°W 0.11 ch., 4) Tamarack 6" S58°W 0.40½ ch.
- 1978 – Consumer's Power Co. Survey drawing #S-F17406 – D. Ankrom, PS #21265 – Found re-rod in tile & scribed cedar post. – 5) 8" Cedar N75°E 14.10', 6) 6" Cedar S80°E 20.50', 7) 6" Cedar S45°E 17.62'.
- 1985 – Certificate of Survey – L. 3, P. 82 – N. Parker, PS #16939 – Conc. Tile Mon.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H5 – ¼ corner common to sections 10 & 15, T26N, R5W

Found 4" X 1' long tile filled with concrete with ½" X 2.3' rebar in center. Dug below tile and found a 3" X 1.3'± long wood post. No Fargo butter dish was found. Found witnesses #5, #6 & #7 fitting position of tile. No GLO evidence was found. Accepted found tile as a **careful and faithful perpetuation of the position of the original corner**, and replaced it with a stamped 4" aluminum DNR cap on 1" x 48" galvanized iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H5 – 4" stamped DNR aluminum cap on 1" X 48" galvanized iron pipe.

N70°E 14.08' to found nail in N. side 9" Cedar (#5)
S84°E 20.34' to found nail in N. side 10" Cedar (#6)
S47°E 17.26' to set nail & tag at fd. nail in NE. side 11" Cedar (#7)
S12°W 9.04' to found nail in E. side 8" Cedar
Set blue post 1' North

Signed by:

Joshua R. Davidson

Date:

DEC. 16, 2014

Surveyor's Michigan License No.:

46659

