



8 0 2 3 2 7 7
Tx:4016447

11/29/2012 1:00:00 PM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Kalkaska Located In _____ Corner Code # _____
(County)

1. Public Land Survey	T	26N	R	6W	18
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Joshua R. Davidson, in a field survey on March 1, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

DOCUMENT #
3111419
JOANN DEGRAAF
KALKASKA CTY ROD
KALKASKA, MI
RECORDED ON
11/29/2012 1:31 PM
REC FEE: 14.00
PAGES: 1
BK: 3PG: 343

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-8 – 1852 – GLO – G. Cannon, Set ¼ Sec. Post

1) Beech 8" S31°W 30

2) Maple 16" N80°E 60

1952 – DNR corner record - Dean C. DeLaMater, PS #5778 – Corner was established by proportionate measurement by Forestry Division survey crew, while making a partial resurvey of this township.

Set 1" pipe with 4" Brass Cap

3) White pine stump N21°E 76 L.

4) White pine stump N78°E 101 L.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-8 – ¼ corner common to sections 22 & 23, T26N, R6W. Found 4" Department of Conservation (DOC) Brass Cap on 1" pipe and witnesses per DeLaMater corner record. No GLO evidence found. Rejected position set by DeLaMater because the position of I7 used to establish the corner was rejected by remonumentation. Set a stamped 4" DNR aluminum cap on 1" x 36" pipe by single proportion between the remonumentation position of I7 and I9. DNR monument is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-8 – A stamped 4" DNR aluminum cap on 1" x 36" galvanized iron pipe.

N28°39'E 7.67' to 1" pipe (DeLaMater – brass cap removed)

N82°E 63.72' to set nail & tag in S. side 7" Red Maple

S30°E 71.62' to set nail & tag in NE. side 7" Red Maple

S68°W 108.22' to set nail & tag in NW. side 22" White Pine

N60°W 13.97' to set nail & tag in SW. side 8" Red Maple

Set blue Carsonite post 1' north



Signed by: Joshua R. Davidson
Surveyor's Michigan License No.: 46659

Date: 11-29-2012