

Document # 3144121 CORN Received: 02/14/2019 03:55 PM Recorded: 02/14/2019 04:04 PM State of Michigan - Kalkaska County Jo Ann DeGraaf, Register of Deeds

Book: 4 Page: 53

Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name:	Joshua R.	Davidson			Field	d Sun	vey Date:	May 2	3, 2018			
For corner(s) in: Kalkask		County			_							
Original Public L	Corner Code											
S 25, 2	26 T	27N R	6W	K10								
S	Т	R				4 В	CD	E F	GН	IJ	K L	M ₁
S	T	R			_ [1	<u>.</u>					
S	тт	R		-	- 2	6-	- +5	4	3 -	- 2	1	2
					_ 3∤				 			3
Property Controlling Corner			Corner Code	4	7 -	8	9	- 10	- 11-	- 12 -	4	
S	T	R _			_ 5	i				ļi	ļ	- 5
S	T	R			- 6	- 1 <mark>8</mark>	- 17	- 16	- 15	14	13-	- 6
s	T	R			- 7							7
S	Т	R				.,						7
					8	19	20 -	- 21	- 22	23	- 24 -	
Property Corner			Corner Code	9			+	+	-		9	
S	T	R			_10	30	29	- 28 -	- 27 -	- 26	25	- 10
S	T	R			- 11	<u> </u>					I -	_ 11
S	Ŧ	R			į	24	20	22	- 34	3.5	26	
S	T	R			- 12	- 31	32	- 33	34	- 35	30	12
		-			13	A B	CD	E F	GH	J	KL	<mark>⊣</mark> 13
Protracted Public Land Survey Corner			Corner Code		•	_						
S	T	R			_							
S	Т	R			_							
S	Т	R			_							
S	T	R										

Part A: Corner History

K10 - 1/2 corner common to sections 25 & 26 T27N R6W

- See remonumentation LCRC L. 6, P. 650 for corner history.
- 2006 Remonumentation LCRC L. 6, P. 650 E. Farrier, PS #24594 Found railroad spike set by E. Farrier pulled and set 5/8" X 18" iron rod with remon cap in centerline road. N78°E 27.10' 14" Poplar, found nail & added nail & washer S52°E 34.82' 8" Poplar, found nail & added nail & washer S82°E 56.38' 26" Maple, found nail N15°W 113.70' power pole, found nail Kalkaska County peer group accepted the above monument as a careful and faithful reestablishment of the position of the original corner.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

K10 - 1/4 corner common to sections 25 & 26 T27N R6W

Found Kalkaska County aluminum monument (5/8" rebar with remon cap) in centerline North-South gravel road. Found two accessories in good condition from Remonumentation LCRC fitting position of the monument. Power pole was gone, found stump of the 26" Maple. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

K10 - 1/4 corner common to sections 25 & 26 T27N R6W

found Kalkaska County aluminum monument (5/8" rebar with remon cap)

N28°E 82.14' to set nail & tag in SE, side 8" maple N78°E 27.16' to found nail & tag in NE. side 13" poplar S50°E 34.80' to set nail & tag at found nail in NE. side 9" poplar S70°W 61.24' to set nail & tag in NW. side 3" ironwood N89°40'E 33.01' to 5/8" rebar & 2" aluminum cap #46659

Certifying Surveyor's Name

February 12, 2019

Date

Professional Surveyor's License No.:

46659

Prepared By: Joshua R. Davidson

Department of Natural Resources

8015 Mackinaw Trail Cadillac, MI 49601

OF MICHIG

JOSHUA R DAVIDSON **PROFESSIONAL** SURVEYOR No. 46659

ROFESSION