

SURVEY & REMONUMENTATION

NOV 23 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Keweenaw

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 57N R 30W

C5

T 57N R 30W

MC C5-D5 (4) ✓

T R

T R

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

REGISTER'S OFFICE

County of Keweenaw } SS

Received for Record, the 12th

day of November A.D. 1996

at 9:00 o'clock A.M., and Recorded

in Liber 149 of LCR

on page 149

Marilyn W. Leinquist
Register of Deeds

Register of Deeds Stamp & File Number

I, Steven C. Hein, in a field survey on June 28, 1996, 19 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C-5) From Original Notes: 80.00 Set post corner of Sections 7, 8, 17 & 18; Cedar 6 N54W 18; do 10 S15E 12: No evidence of original corner or accessories.

(C-5/D-5)M.C. From Original Notes: 15.90 Intersected Lake Set Meander post; Cedar 9 S76W 39; Spruce 7 N81 1/2W 38: No evidence of original corner or accessories.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-5) Found 1" pipe as recorded on L.C.R. liber 1, Page 95: Witnesses: 9" Balsam N50E 9.96'; 10" Cedar S74E 16.45'; 6" Cedar S05E 16.73'; 8" Cedar S73W 20.66'

(C-5/D-5)M.C. Found 3/4" pipe, 31' West of Gratiot Lake and 8.3' Northeasterly of cabin wall, as recorded in L.C.R. Liber 1, Page 95: Witnesses: 12" S. Maple S61E 15.02'; 6" Balsam S11W 28.12'; SW Cor. Cabin S13W 10.40'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C-5) Accepted location of 1" pipe,
Replaced with 4" Remon. Brass Cap
stamped for corner

Accepted old Witnesses:

9" Balsam N50E 9.96'

10" Cedar S74E 16.45'

6" Cedar S05E 16.73'

8" Cedar S73W 20.66'

Note: Wit. have nail in side blaze.

(C-5/D-5)M.C. Accepted location of 3/4"
pipe, Replaced with 4" Remon. Brass
Cap stamped for corner

Witnesses:

13" R. Maple S60E 15.27'

8" Balsam S12W 28.15'

15" W. Birch N53W 30.90'

10" Balsam N21W 44.76'

Note: Wit. have tag #32336

Ratified by Peer Group
In accordance with P.A. 345
Co. Rep. *James M. Leinquist*
Date 10/15/96



Signed by Steven C. Hein

Date SEPTEMBER 13, 1996

Surveyor's Michigan License No. 32336