## SURVEY & REMONUMENTATION

MAR 1 9 1997

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

		Filing Requi	rement of Act 74, Mich. I	P.A. 1970
For	corners in			REGISTER'S OFFICE
	Keweenaw	Located In:	Corner Code ≠	County of Keweenaw SS
	(County)		3011101 3343 475	Received for Record the 9th
				Received for Record, the 9th.
1	Public Land Survey	т <u>58</u> в <u>29</u>	G/H 3 ((1))	USV OI DAAGO L.
	t abite cana carrey	T 58 R 29	1 - 4/5/61	UCIOCK F. M. and D.
			<del></del>	in Liber 1 of 1 C P
		T A		of LCR
		T R		A page No
2.	Property Controlling	S T R	j	Bobenta Rosenburger Deze
-	in Section			Register of De
_		S T R		G 0. Do
3.	Miscellaneous	S R	<del></del>	Register of Deeds Stamp & File Numbe
	Property in Sec.	S T R		
				Ü
4.	Lot No,	Recorded Plat		ABCDEFGHIJK
5.	Private Claims			
				2 6 1 5 1 4 1 3 1 2
				3 1 1 1 1 1 1
	John I Haataia	N -		4 - 7 - 6 - 8 - 1 - 9 - 1 - 10 - 1 - 11 - 1
1,	ouiii 1. naataja	, in a field survey onNo	<u>ovember 14 , 19 96</u>	<u> </u>
do h	iereby certify that under r	equirements of P.A. 74, Michigan P.A	of 1970, the corner points ment	ioned 6 19 17
in II	nes 1 and 2 above were	in conformance with regulations ar	id rules therefore as required	in the
curr	ent manual of survey ins	tructions of the United States Depar	tment of the interior, Bureau of	Land 7
Man	agement or by a decree o	of a Court of Law and/or that the corne	er points mentioned in lines 3, 4	and 5
abov	ve were in conformance v	with the rules of the Michigan Board o	of Land Surveyors or by a Decre	Pe 018
Cou	rt of Law; established,	re-established, monumented, re-	nonumented, recovered, four	nd as
expr	essed below:			10 30 29 28 27 26
NOT	E: Not more than 4	corners, all in the same town as	od range, may be recorded	
	on this certificate		in lange, may be recorded	· · · · · · · · · · · · · · · · · · ·
	On this certificate	z.		12 31 32 34 35
				13
Λ.	Description of original	monument and accessories and	d/or subsequent restoration	
	Wood P White	r corner between 3 & 10 ost at high water mark Pine 12" S 50 E 37 1ks 10" N 41 E 27 1ks	•	Meander corner between 10 & 11. Wood Post Spruce 9" S 46 E 16 1ks.
•	G/H - 3 No evid FND. F betweer S.W. co	dence of original corne Re-established on line in S.E. cor. Sec. 3 and or. Sec. 4	JOHN I. HAATAJA LAND SURVEYOR NO. 19833	No evidence of original corner FND. Re-established during survey of Assessor's Plat of Lake Medora. This is on line between N.E. cor. & S.E. cor. of Sec. 9 & on intermediate traverse line of the Plat.  Ratified by Peer Group in accordance with P.A. 345 CO. Rep.
D	escription of monumer	nt for corner and accessories as	tablished to name to the	Vale 146/46
,		nt for corner and accessories es	manage to hethernare loca	ating the position of the corner:
G,	6" Cedar 16" Cedar 4" B. Fi 8" Cedar	corner between Sec. 3 Dipe with brass cap N 58 W 9.69' N 28 E 7.66' Tr S 51 W 10.93' S 69 E 13.85' to waters edge	S L C D D	Meander cor. between 10 & 11.  Let 1" pipe with brass cap flush Lot Pin N 73 W 40.51' Lonc. Mon. S 73 E 56.73' Leck Post/Tag S 16 E 8.60' Leck Post/Tag S 73 W 43.57' Lock Post N. to waters edge
ned	by Ars Michigan License	- C Amolay		11/27/96

FORM APPROVED BY MICHIGAN STATE EGARG OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975