

NOV 21 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED  
LAKE COUNTY, MI.

LIBER 004 PAGE 0040  
SEP 12 10 31 AM '97

REGISTER OF DEEDS

For corners in

Lake (County)	Located in:	Corner Code #
	17N 13W D-5	
1. Public Land Survey	T R	
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

Robert L. Wetherell

July 2, 97

I, in a field survey on 19 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-5 - 1/4 Corner common to Sections 8 and 17, T17N, R13W, Lake Co., Mi.

1838 - J. Hodgson, G.L.O.

#1 - 8" W. Oak S78° 30 Links

#2 - 6" W. Oak N15°E 25 Links

1941 - George Blass, LS 5489

Found Angle Iron

#3 - 16" W. Oak S35°W 27.6'

#4 - 12" Tw. W. Oak S37°E 35.0'

#5 - 10" B. Oak N83°E 30.6'

Undated - Co. Survey Records

#6 - 14" W. Oak N3°W 83.8'

1972 - Robert Griffin, LS 13584

L.C.R.C. - Liber 02, Pg. 94

Found Angle Iron- Replaced with  
5" Square Concrete Monument

#7 - 5" W. Oak N60°E 63.18'

#8 - 12" W. Oak S47°W 66.15'

#9 - 3" R. Pine N46°W 54.84'

#10 - Square Post - North 33.06'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-5 - 1/4 Corner common to Sections 8 and 17, T17N, R13W, Lake Co., Mi.

I found the 5" Square U.S.F.S. Concrete Monument 12 feet North of East and West dirt road.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 gone, #4 Found in good condition, #5 Found in poor condition, #6 gone #7 Gone, #8 Found dead, #9 Found in good condition, #10 Found in good condition.

RATIFIED BY THE LAKE CO. PEER REVIEW GROUP  
IN ACCORDANCE WITH P.A. 345  
CHAIRMAN R.L.W.  
DATE 8-27-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-5 - 1/4 Corner common to Sections 8 and 17, T17N, R13W, Lake Co., Mi.

I accepted the 5" Square Concrete Monument as a substantial marker for the corner, and is accepted as a careful and faithful re-establishment of the position of the original corner.

6" W. Pine S34°W 58.74' (60d spike in S.E. side)

11" W. Oak S27°E 52.04' (60d spike in E. side)

6" R. Pine N42°W 55.02' (dock spike in E. side) #9

8" R. Oak N42°E 45.09' (60d spike in S.E. side)

Signed by Robert L. Wetherell

Date 8-27-97

Surveyor's Michigan License No.

