

JAN 5 2000

Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970-1971

PAGE 390

STATE OF MICHIGAN  
LENAWEE COUNTY  
FILED

SECTION

For corners in

Lenawee  
(County)

Located In:

Corner Code #

14 DEC 1999 4:33:37 PM

VICTORIA J. DANIELS  
REGISTER OF DEEDS

1. Public Land Survey	T	R	
	T	R	
	T	R	
	T	R	
2. Property Controlling in Section	S	T	R
	S 19 & 30 T - 5 - S	R - 3 - E	4
3. Miscellaneous Property in Sec	S	T	R
	S	T	R

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, Glenn E. Richard, in a field survey on November 29, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. This corner not established by original government surveyors

This corner is not shown on the GLO Plat but the patents for the SW 1/4 of Section were for the West and the middle division of the SW 1/4 of Section 19.

1964 &amp; 1973 Surveys and descriptions by Walter Frazier in Section 30 call for the centerline of Pentecost Highway.

1989 Werner Sommer prepared the plat of Limerick which is recorded in Liber 19 on Pages 40 &amp; 41. This plat shows this as being the East line of West subdivision NW fractional 1/4 Sec. 30. He set a iron pipe in the pavement at the intersection of the centerline of Pentecost Hwy. as per the Walter Frazier surveys and a line between the S 1/4 corner and the Southwest corner of Section 19

1989 Dean Gutekunst found iron pipe

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

August 11, 1999 I found iron pipe under base course of asphalt and set monument box to be level with final asphalt course.

November 29, 1999 Replaced the found iron pipe with 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box .

Plat monument N 45° W 45.81

Plat monument West 33.00

Cut "X" on N.E. CMP N 30° E 57.19

MAG nail &amp; re-mon tag in EP East 33.39

SW corner Section 19 (now under Loch Erin) West 1840.06

S 1/4 corner Section 19 ( 1 1/2" X 3' IP recorded in Liber 5, Page 105) East 3152.66

Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date December 7, 1999Signed by Glenn E. Richard Date Dec. 8, 1999  
Glenn E. RichardSurveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993