

JAN 2 2 2001

Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

	SECTIO	Ŋ	Į.					.iber 1		PAG	E 399
For corn				HI 1998 1	1111111	I <b>R</b> 1		ו ווטבוו	STATE	OF MIC	
Lenawe	(County)	Located In:	Corner Code #							FILED	
1 Dahli	ic Land Survey	T-5-S R-3-E	A-13					28	JUN 20	900 8	42:54 Rh
1. Lani	c Land Survey	T <u>55 R25</u> T68 R35	M-/3							IA J. E ER OF	DANTELS DEEDS
in Se 3. Misc	erty Controlling ection ellaneous erty in Sec	T 6S R 2 5 S T R S T R S T R S T R	M-I	Re			)eeds				
					1 1		, D E	: r (	э H I	J	C L M
		Recorded Plat			2	6	5	4	3	2	1
5. Priva	ite Claims				3						
					5	7	8	9	10	11	12
1, Glenn E. Richard in a field survey on May 16, 2000 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						18	17	16	15	14	13
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5.					8 9	19	20	21	22	23	24
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				Decree of a	10	30	29	28	27	26	25
					11 12	31	32	33	34	35	36
NOTE:	Not more than 4 on this certificat	corners, all in the same town	and range, may be recor	ded	13	)	32	33	34	35	30
A. De	escription of origi	nal monument and accessories	and/or subsequent resto	ration:							
	Late 1800's In 1953 Werner S bricks & stone a 1958 Kenneth 1973 Werner S 1975 Werner S 1978 Kenneth 1983 Werner S (called for in Blates) 1993 Werner S 1995 Michael E	and Benjamin Hough D.S. es J. Blair's records described the Gommer while employed by Waround it and another iron pipe Suydam found iron pipe and recommer found iron pipe and suydam found iron pipe and Suydam found iron pipe and Suydam found iron pipe and Sommer set a 1" X 10" iron pipe airs records) and recorded it is Gommer found 1" iron pipe Bartolo found 1" iron pipe alor in Liber 5, Page 267 for M-1	e corner as "Stone & br /alter Frazier found bric e at the surface ecorded it in Liber 2, Pa recorded it in Liber 3, Pa recorded it in Liber 4, Pa pe over large stone by a in Liber 5, Page 89 for N	ricks in north  As in north  Age 453 for  Age 155 for  Age 139 for  Age 139 for  Action of the sextending lift  A-13 5-2	A-1 M-1 A-1 M-1	ad ditu 6-3 1 6-2 13 5-3 yest 2	ch= SI , set ii 26.49'	E corr on pi	ner Se be 2' d	ction : leep 8	36" k placed ggy axle
B. De	escription of corn	er evidence found and/or meth	od applied in restoring or	reestablishi	ing c	orner:					
	May 16, 2000 I diameter stones the stone over a	ound 1" iron pipe as recorded Found 1" X 10" iron pipe on to s around it. While digging to another iron pipe 2' deep 0.45 0" I.P. over stone	op of stone 14" X 10". Senlarge the hole I found	Split it to ge l a 3/4" X 1	t out 5" si	olit se	am iro	n pipe	0.36	south	beside
C. De	escription of monument for corner and accessories established to perpetuate locating the position of the corner:										

В.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:
	May 1, 2000 Found 1" iron pipe as recorded by M. Bartolo in Liber 5, Page 267 May 16, 2000 Found 1" X 10" iron pipe on top of stone 14" X 10". Split it to get out of hole. Several other 4" to 6" diameter stones around it. While digging to enlarge the hole I found a 3/4" X 15" split seam iron pipe 0.36 south beside the stone over another iron pipe 2' deep 0.45 south surrounded by bricks. Set 30" Harrison monument @ location of the found 1" X10" I.P. over stone
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:
	30" Harrison Monument stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.  2' North of N. edge of gravel road & 6" below level of road Fd dbl hd nail & disc in E.P. S 70° W 78.99  S. edge of Carsonite post North 0.53  Center of top on tele. pedestal S 35° E 67.15  Stop sign post S 20° E 64.90  Face of Road sign post S 35° W 43.03  Fd. nail & disc in E. P. S 20° W 94.24  1 1/4" iron pipe over buggy axle S 76° E 226.52
Ratifi	ed by Peer Group in accordance with P.A. 345 Co. Rep Henri Rukard Date May 9, 2000
Signe	ed by Peer Group in accordance with P.A. 345 Co. Rep Henne Ruhard Date May 9, 2000  Od by Henne Ruhard Date June 5, 2000  Glenn E. Richard
Surve	SYOT'S Michigan License No. 13040 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 197 REVISED JAN., 198 ADAPTED FOR WORD PROCESSING MARCH, 199