

JAN 2 2 2001

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Lenawee

(County)

Located In:

Corner Code #



LIBER 1

PAGE 405

STATE OF MICHIGAN
LENAAEE COUNTY
FILED

28 JUN 2000 8:42:54 AM

VICTORIA J. DANIELS
REGISTER OF DEEDS

1. Public Land Survey T 7 - S R 4 - E J-9
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec S _____ T _____ R _____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on January 13, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management, or by a decree of a Court of Law, and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1819 Joseph Fletcher set 1/4 Sec. post B. Oak 16 S 6 W 21 Lynn 10 N 42 W 6
1882 James Blair found stake
1883 James Blair found stake
J.L. Richard's record is copy of Blair's survey
1958 & 1960 Walter Frazier used center of wood post for line to north
1966 I used the east edge of the post to sight to from the South.
1972 I set a iron pipe on the east side of a post which checked Blair's distance to East 1/4 corner
1990 I found iron pipe on east side of post
1999 The iron pipe was gone and a tall large post has been set 1'± SE of the original post.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

January 13, 2000 I retraced my 1972 survey and set a 30" Harrison monument

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison monument stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

Carsonite post West 0.41
Face of Wood post S 30° E 0.52
East 1/4 cor. East 2647.03
Re-rod on North and South 1/4 line @ South edge of woods North 572.61
Re-rod in south line of R.R. R.O.W. North 1700.87
Re-rod 60'± north of centerline of US-223 South 1492.39'



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date May 9, 2000

Signed by Glenn E. Richard Date June 5, 2000
Glenn E. Richard

Surveyor's Michigan License No. 13040