

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 36 T 45N R 10W S _____ T _____ R _____ S _____ T _____ R _____	7
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/18/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(7-Sec. 36) North 1/16 corner between Section 36 T45N-R10W and Section 31 T45N-R09W. 1981 -
Established by David B. Babbitt RLS midway and on line between section corner to North and 1/4 corner
to South. Set 1" pipe with 4" aluminum cap. 28" Hemlock S62E 60.0', 10" R.Maple S16W 27.8', 6"
R.Maple N66W 10.0'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(7-Sec. 36) Found the 1981 monument in good condition and at record bearing and distance from the
1981 BT Maple S16W 27.8', in good condition. Accepted the monument as a careful and faithful
establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(7) Fd. 1" ID I.pipe with 4" alum. MI Dept.
of Conservation cap.
Set measuring nail with MDNR tag in the side of:
21" Maple S20W 27.6' mrkd "N1/16" 1981 BT
10" Sugar S21E 12.7' mrkd "N1/16 BT"
16" Cherry S87E 8.6' do
15" W.Pine N27E 39.1' do
Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/12/2012

For the Michigan Department of Natural Resources, Forest Resources Division