

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 9 T 45N R 10W C-E-NW 1/64 S 9 T 45N R 10W 5 S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 11/29/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C-E-NW 1/64 corner, Section 9) The SE corner of the SW1/4 of the NE1/4 of the NW1/4 of Section 9. Not established in the original survey.

(5-Sec. 9) The North 1/16 corner, Section 9. Previously monumented by Larry Rogers RLS, date unknown. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-E-NW 1/64) Established the corner midway and on a straight line between 1/16 corners #4 and #5, Section 9.

(5-Sec. 9) Found a 1/2" dia. rebar with plastic cap stamped "LRR 29251" in good condition and at the proper position, midway and on line between Quarter corner to the North and the Intersection of 1/4 lines of Section 9 to the south. Accepted the monument as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1/64) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
11" Sugar N34W 14.05' mrkd "1/64 BT"
20" Hemlock N57W 28.9' do
13" Sugar S05W 11.5' do
10" Y.Birch N35E 17.5' do
Bearings are magnetic.

(5) Fd. 1/2" rebar with plastic cap 'LRR 29251' Set measuring nail with MDNR tag in the side of:
8" Sugar S76E 5.05' mrkd "N1/16 BT"
7" Ironwood N15E 14.7' do
12" Sugar N59W 12.7' do
5" Sugar S29W 19.45' do
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/10/2011

For the Michigan Department of Natural Resources, Office of Land and Facilities



47467

47468

FORM APPROVED BY MICHIGAN STATE BOARD OF

1971
14, 1975
Jan., 1983
Revised Oct., 1995