

MAR 13 2000

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970  
Luce County Remonumentation Corner

**SECTION**

For corners in

Luce County

Located in:

Corner Code #

1. Public Land Survey

T45N R10W

D/E-5

#4

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

4. Lot No.

, Recorded Plat

5. Private Claims

LUCE COUNTY  
REGISTER OF DEEDS

Recorded

*Liber 3 Page 904*  
02-08-2000 13:01:28

*Kathy S. Mahan*  
Kathy S. Mahan, Register  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on November 12, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D/E-5 Witness Corner to Meander Corner Between Sections 8 & 17, T45N, R10W on the West Side of Kak's Lake

1849 - Original corner established by William Ives, 66.7 chains east of the section corner at C-5, 26.7 chains east of the 1/4 corner at D-5.

Witnesses: Tamarack 7, S37°W 108 links - Tamarack 6, N60°W 74 links.

Found no evidence of subsequent restoration of this corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Luce County Remonumentation Program.

Found no evidence of the original corner. Reestablished corner on the west shore of Kak's Lake, on a line from the section corner at C-5 towards the computed position of the section corner at E-5, which falls in Kak's Lake. The section corner at E-5 was computed at a pro-rated location according to the original GLO notes between the meander corners on the north and south sides of Kak's Lake. (2029.5 feet GLO, 2002.9 feet measured, between said meander corners). The corner was placed 4214.29 feet east of the section corner at C-5, which is 187.91 feet west of the record GLO position, which now falls in Kak's Lake.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 1/2" x 18" rebar with a stamped aluminum Luce County Remonumentation cap at the corner location, on the west shore of Kak's Lake.

Witnesses:

Nail and tag #33142 in 7" blazed White Birch, S83°E 16.84'

Nail and tag #33142 in 4" blazed Balsam Fir, S50°E 14.50'

Nail and tag #33142 in 4" blazed Balsam Fir, S37°W 12.11'

Nail and tag #33142 in 4" blazed Balsam Fir, S83°W 21.91'

Signed by

*Keith R. Waters*

Date

*12-29-99*

Surveyor's Michigan License No. 33142