

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S <u>21</u> T <u>45N</u> R <u>11W</u> S _____ T _____ R _____ S <u>21</u> T <u>45N</u> R <u>11W</u>	F8 (GCDB 340340) 12 (GCDB 340320)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 11/20/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F8) Center of Section 21. Not previously monumented.

(12-Sec. 21) South 1/16 corner, Section 21. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F8) Established the position for the corner at the intersection of straight lines connecting
opposite 1/4 corners.

(12-Sec. 21) Established the position for the corner midway and on a straight line between Quarter
corner 1305.99' south and the Center of Section 21 1305.99' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F8) Set 5/8"x24" rebar with plastic cap stamped "MI
DNR PS33986" in pavement of County Road 429.
Centerline of Co.Rd. is 7.8' west.
Set measuring nail with MDNR tag in the side of:
5" Cedar N66°W 54.65' mrkd "CS BT"
8" Cedar S55°W 68.35' do
6" Cedar S62°E 36.3' do
8" Cedar N62°E 44.8' do
E= 8101164.333 N= 167324.536

(12) Set 5/8"x24" rebar with plastic cap stamped
"MI DNR PS33986". The monument falls on the east
edge of the pavement of Co. Rd. 429.
Set measuring nail with MDNR tag in the side of:
6" Cedar S74°W 73.05' mrkd "S1/16 BT"
12" twin Cedar N40°W 65.75' do
14" Cedar S80°E 37.2' do
7" Maple N55°E 48.7' do
E= 8101173.070 N= 166926.619

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID D08495: N= 169938.252 m. E= 8114556.094 m.

Signed by Stephan J. Szyszkoski

Date 04/21/2014

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division