

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S <u>15</u> T <u>46N</u> R <u>12W</u> S _____ T _____ R _____ S <u>15</u> T <u>46N</u> R <u>12W</u>	<u>5</u> (GCDB 440460) <u>7</u> (GCDB 500460)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 05/07/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 15) Center-North 1/16 corner, Section 15. 1977 - Established by Gerald W. Carlson PS, rec.
L1 LCRC P17. Set 5/8"x18" capped rebar. 9" J.Pine S20°E 43.73'; 5" tw. Maple N17°W 15.75'; 5"
Birch Cluster [no bearing or dist. given].

(7-Sec. 15) North 1/16 corner between Sections 14 & 15. 1977 - Established by Billy D. Buckler RLS
midway and on line between Section and 1/4 corners. Set 1" pipe with 4" alum. Cap. 6" Maple N26°W
19.7'; 6" Beech S48°E 35.8'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5) Found a 1/2" iron with illegible plastic cap at record bearing and distance from the 1977
witness J.Pine [this is actually a Red Pine] and twin Maple, both in good condition. Verified the
position of the monument as being substantially midway and on a straight line between monumented H5
and H6 and accepted same as a careful and faithful establishment of the position of the corner.

(7-Sec. 15) Found the 1977 monument in good condition and substantially at the record position. The
1977 witness trees were not recovered. Accepted the monument as a careful and faithful
establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Found 1/2" capped rebar.
Set measuring nail with MDNR tag in the side of:
15" R.Pine S20°E 43.81' mrkd "N1/16 BT"
8" W.Pine S66°E 28.78' do
9" W.Pine N40°E 42.24' do
7" Maple N18°W 15.89' do
E= 8092917.544 N= 178872.924

(7) Found 1"ID I.pipe with 4" alum. State of MI
cap. Set measuring nail with MDNR tag in:
6" Maple N80°W 14.46' mrkd "N1/16 BT"
5" Maple S12°W 8.38' do
6" Maple S56°E 14.02' do
6" Balsam N16°E 9.43' do
E= 8093727.127 N= 178896.153

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 date
Coord. Ref.=NGS PID RJ1233: N= 183112.192 m. E= 8082067.781 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/10/2015

For the Michigan Department of Natural Resources, Forest Resources Division

