

OCT 11 1994

COMMISSION

MACKINAC COUNTY REMONUMENTATION CORNER  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Mackinac  
(County)

Located In: Corner Code ##

1. Public Land Survey

T 40N R 4W

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling  
in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous  
Property in Sec.

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

#10

RECEIVED & FILED  
DIANE FRAT KOVICH  
MACKINAC COUNTY CLERK OF DEEDS

SEP 6 1994 PM  
AJA  
7/8/9/10/11/12/13/14/15/16

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Neil E. Hill August 22 94

I, \_\_\_\_\_, in a field survey on \_\_\_\_\_, 19\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Set 8" cedar at 7.73 chains South of I-7

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No record of corner  
Surveys in the area by TL Jackson and Feindt  
1994 found 1" pipe  
6" Basswood North 16.33' (face)  
10" Cedar S68E 10.75' (face)  
24" Tw. Cedar S43W 07.55' (face)



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted 1" pipe as found; removed and placed with 5/8" re-rod with 4" aluminum cap.  
8" Basswood North 16.65' (nail in side)  
10" Cedar S68E 11.05' (nail in side)  
24" Tw. Cedar S43W 08.32' (nail in side)  
10" Spruce N55W 22.41'

ACCEPTED BY THE MACKINAC COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER P.A.  
345 OF 1990 AT A MEETING  
HELD ON 8-16-94

*James H. [Signature]*

Signed by Neil E. Hill P.S. Date August 22, 1994  
Surveyor's Michigan License No. 27447