

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

MACKINAC CO, 3 corners.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 42N N. S., R. 6W E. W.	I-6
2. PROPERTY CONTROLLING IN SECTION 15	T. 42N N. S., R. 6W E. W.	7-SEC.15
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	14-SEC.15
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 04/22, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

I-6; Quarter Cor. bet Secs. 14-15, set by H. Brevoort Jr. D.S 1845  
Bearings were: Beech 8" S48'E, 26LKS and Birch 8" N65'W, 21 Lks.

7-SEC. 15; North 1/16 Corner, on East side cSec. 15.

14-SEC. 15; South 1/16 Corner on Eastside, Sec. 15.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-6; Corner re-established midway and line bet two Sec. Cors.  
Noevidence of original Corner.

7-SEC.15; Corner placed midway bet. Sec Cor. to North & 1/4 to South.

14-SEC. 15; Corner placed midway bet. Sec. Cor. to South and 1/4 Cor. to North.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" Pipe with 4" Aluminum Cap at all corners.

I-6; New Bearings: 8" Maple, N5'E, 8.8' and 8" Maple, S54'E, 17.6'.

7-SEC, 15, New Bearings; 10" Maple, S73'E, 12.8' and 8" Maple, S31'W, 10.1'

14-SEC.15; New Bearings 8" maple, S22'E, 4.8' and 6" Maple, N74'E, 10.2'.

SIGNED BY

Billy D. Buckler  
Billy D. Buckler

DATE 7/27/76

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

