

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Macineac

Located In:

Corner Circle //

1. Public Land Survey

T 42N R 7W

M3

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous
Property in Sec

S _____ T _____ R _____

S _____ T _____ R _____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Stephan J. Szyszkoski, in a field survey on August 17, 1993, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	13	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

(M3) Section corner common to sections 1-12, T42N-R7W, and sections 6-7 T42N-R6W. Corner recorded by Billy D. Buckler, RLS in 1964 as follows: This corner was re-witnessed as set by D. Brotherton, Land Surveyor about 1915, during alignment survey of old U.S. #2. 3/8" iron bar driven beside 2" iron pipe set in concrete. Witnesses: 12" H. Maple (S7 NBT) S70E 18.3', 12" H. Maple (S6 NBT) N38E 29.1'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M3) Found and accepted monument and accessories as described above. Buckler's NBTs are still green and in good condition. Marked new top blaze on the 1964 NBTs, placed measuring nails with tags in same, and remeasured as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M3) Found 3/8" iron bar.
18" H. Maple S70E 18.3' (1964 NBT)
16" H. Maple N38E 29.75' (1964 NBT)
new witnesses:
Power Pole (#12-J72-SPD540) N40W 34.4'
nail and tag.
Brace pole for above N24E 27.4' nail
with MOOT tag.
Corner lies at east edge of a road.



Signed by

Stephan J. Szyszkoski

Date

10-14-93

Surveyor's Michigan License No.

33986