

SURVEY &  
REMONUMENTATION

MAR 13 1998

SECTION

1997 Mackinac County Remonumentation Corner  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 43N R 1W

G-12

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Property in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

RECEIVED & FILED  
DIANE PLATT KETCHUM  
MACKINAC COUNTY CLERK

DEC 31 1997

AM 7:18 PM 12/31/97

Register of Deeds Stamp & File Number

I, David B. Guthrie, in a field survey on July 18, 1997,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845: G.L.O. Survey by J.H. Mullett - Set Post and Referenced -  
Beech 20 / S85E / 41  
Beech 20 / S48W / 45

1994: Survey by Ronald Bischer - Found 1/2" Iron Rod by Harry Goodwin and three witnesses.  
Referenced -  
N81°E - Fe. Post - 32.45'  
West - 1" Pipe - 33.00'  
N60°W - 9" Beech - 50.20'  
S38°E - 12" Beech - 45.12'  
L.C.R.C. Recorded in Book D, Page 264.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997: Remonumentation Survey by R.S. Scott Associates, Inc.  
Found 1/2" Iron Rod 0.8' East of road centerline.  
Referenced -  
(Exist.) N65°W - 12" Beech - 50.16'  
(Exist.) S85°W - 4" Beech - 46.00'  
S35°E - 18" Beech - 45.52'  
N70°E - 21" Beech - 37.25'

This corner position is compatible with County and local surveys. This corner  
position is accepted as a careful and faithful perpetuation of the position  
of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1997: Placed 3" Mackinac County Cap stamped to identify the corner over 1/2" Iron Rod  
in Monument Box.  
Referenced -  
N65°W - 12" Beech - 50.16'  
S85°W - 4" Beech - 46.00'  
S35°E - 18" Beech - 45.52'  
N70°E - 21" Beech - 37.25'

ACCEPTED BY THE MACKINAC COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER PA.  
345 OF 1990 AT A MEETING  
HELD ON 11-21-97



Signed by

David B. Guthrie

Date

12-19-97

Surveyor's Michigan License No.

22435

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983