

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
Mackinac Co. 3 Corners.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY.....	T. <u>43</u> N. R. <u>6</u> K. W.	K-8, M-10, E-12
2. PROPERTY CONTROLLING IN SECTION.....	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION.....	T. S. R. E. W.	
4. LOT NO., RECORDED PLAT.....		
5. PRIVATE CLAIMS.....		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 4/25 & 4/27, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19....., found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
All corners set by H. Brevoort Jr., D.S. in 1845.

K-8 $\frac{1}{4}$ Cor. bet. sec's. 23-24. M-10 $\frac{1}{4}$ Cor. on Eastside Sec 25. E-12 $\frac{1}{4}$ Cor. bet. Sec's. 32-33.
Bearings were: Bearings were:
Balsam 12, S57°W, 18 lks. Pine 22, $\frac{1}{4}$ Sec. Cor. Hem 8, N22°E, 15 lks.
Maple 12, S18°E, 22 lks. Pine 22, West, 9 lks. Hem 10, N31°W, 20 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
K-8 Found 2" iron pipe placed by Marcus Schaaf, R.L.S. in 1939, from line tree to North and South.
M-10 Replaced corner in site of a W. Pine stump with another W. Pine stump at proper bearing and distance. Found notes by Marcus Schaaf, R.L.S. He found this corner in 1937. Corner lies 115' North of a Pine Plantation corner and in line with an open lane to West.
E-12 Found wood stake in ground. Distance South to corner, $\frac{1}{2}$ mile checks well. No evidence of original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
K-8 re-witnessed corner. M-10 and E-12 placed 1" pipe with 4" aluminium cap.

K-8 New Bearings:	M-10 New Bearings:	E-12 New Bearings:
12" R. Pine, S66°E, 11.3'	6" J. Pine, S44°W, 16.9'	24" W. Pine, N30°W, 23.6'
9" R. Pine, N28°E, 3.8'	5" B. Spruce, N65°E, 9.7'	16" W. Pine, N37°E, 24.4'

SIGNED BY

Billy D. Buckler
Billy D. Buckler

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO.

