

SURVEY & RECORDATION

FEB 18 1994

COMMERCIAL

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac

(County)

Located In:

Corner Code #

1. Public Land Survey

T 43NR 2W

C-1

T R

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECEIVED & FILED
DIANE PRATT-KOCH
MACKINAC COUNTY, MICHIGAN

DEC 07 1993

AM

PM

7/8/93 11:11-11:13/45/6

Register of Deeds Stamp & File Number

Neil E. Hill

October 1

93

I, in a field survey on , 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1840: Established by William A. Burt, in the original government survey of T43N, R02W. Set wood post and established the following references:
16" Cedar N37E 35 Links 18" Sugar N15W 34 Links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1988: No original or subsequent corner evidence was recovered. The corner position was re established by the single proportionate measurement on the line between the recovered Northwest Corner of Section 6, and the recovered Northwest Corner of Section 4.

1989: A 2-1/2" x 3' aluminum monument with a 3" aluminum cap stamped to identify the corner was set by Richard L. Nays L.S.#25847. Monument was set 2" above the ground with the distance taken to nail blaze. Established the following references, of which the bearing trees are blazed, scribed and painted red:

5" Maple N64E 15.05 feet
4" Maple S03W 3.51 feet
Post East 1.50 feet

5" Maple N41W 11.44 feet
12" Maple S35E 42.88 feet

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: Found a 2-1/2" x 3' aluminum monument with a 3" aluminum cap stamped to identify the corner. The following references, of which the bearing trees are blazed, scribed and painted red were found:

5" Maple N64E 15.05 feet
4" Maple S03W 3.51 feet
Post East 1.50 feet

5" Maple N41W 11.44 feet (nail facing corner)
12" Maple S35E 42.88 feet


1993: Upon review, the location and witnesses for the corner as recorded in Liber D-001 (Corner Records), are sufficient to perpetuate corner location.

Signed by Neil E. Hill P.S.P.C.

Surveyor's Michigan License No. 27447

Remonumentation Surveyor

D-0230



October 15, 1993

REVISOR MAY 14, 1975
REVISED JAN., 1983