## SURVEY & REMONUMENTATION

APR 2 8 1995

## LAND CORNER RECORDATION CERTIFICATE

C105008

For corners in COMMISSION	Filing Requirement of Act 74, Mich. P.A. 1970 Washington		C109009						
Macomb (County)	Located In: Township Corner Code =	#	94,	LIBER	)64	15P	648	35	
Public Land Survèy	T 4 N R 12 E I-10  T R  T R  T R	L.	CARI REGI MACO	LIBERY NUG -	5 PM	1:4 AUGH EDS	.3		
in Section S	T R				, 17	, MI			
	T R	Registe	er of D	eeds S	tamp	& File	Num	ıber	
	t Plat		6	C D	E F	G H	2	K	<u>L</u>
in lines 1 and 2 above were in conform current manual of survey instructions of Management or by a decree of a Court of above were in conformance with the rule	seld survey on	19 94 , 5 ints mentioned equired in the bureau of Land ines 3, 4 and 5 y a Decree of a	18	-17	28	15	23		13-24-25
NOTE: Not more than 4 corners, a on this certificate.	all in the same town and range, may be re	11 12 13	31	32	33_	34	35		36
1817-GLO Wampler, D.S.; Set Post 1: 1.) 1973-Kobs, P.S. #14097; LCRC 1 2.) 1978-DeWinter, P.S. #25839; LG 3.) 1973-Kobs, P.S. #14097; Survey 4.) 1973-Kobs, P.S. #14097; Survey 5.) 1973-Kobs, P.S. #14097; Survey	nt and accessories and/or subsequent res L* Sugar N34*W 16 Links; 10* Beech S08*E 7 L.2360, Pg.812 - Fnd 1/2* Iron Bar in a MoCRC L.3031, Pg.885 - Fnd 1/2 Iron V L.2360, Pg.827 - Same wit as 1973 LCRC V L.2360, Pg.829 - Same wit as 1973 LCRC V L.2360, Pg.831 - Same wit as 1973 LCRC V L.?, Pg.? - Same wit as 1973 LCRC	Links					·		

8.) 1977-Kobs, P.S. #14097; Survey L.2881, Pg.429 - Same wit as 1973 LCRC
9.) 1978-DeWinter, P.S. #25839; Survey L.3031, Pg.882 - Fnd 1/2" Iron Bar in a Monument Box

7.) 1973-Smith, P.S. #18052; Survey L.2699, Pg.498 - Same wit as 1973 LCRC

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1994 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 1/2" Iron Rod in a Monument Box 3' West of the centerline of Jewell Road, which has a gravel surface, with a tree-fence row extending to the East, and 35' North to the driveway for house #60065.

Witnesses from LCRC #1 & 2 were used to recover and verify the location of the found 1/2" Iron Rod in Monument Box.

## FIELD NEASUREMENT BETWEEN

I-10 to I-9 2785.16 Feet I-10 to I-11 2639.10 Feet I-9 to I-10 2785.16 Feet ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 346 OF 1990 AT A MEETING HELD

WILLIAM E. SODERBERG, P.S., CHAIRMAN

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- I-10 I replaced the found 1/2" Iron Rod in a Monument Box with a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 \$17623" in a existing Monument Box.

S43 B 50.58' Set PK & Remon. Washer SW face 18" triple Ash

Due West 31.21' Set PK & Remon. Washer South face Power Pole

N86'W 50.68' Set PK & Remon. Washer SW face 10" Pine

S74'W 38.85' Set PK & Remon. Washer NW face 9" Maple

The selected location is accepted by me and is generally accepted by Professional Surveyors as the position of the original corner.

HUSTON
KENNEDY
as the best ROFESSIONAL
17623

21, 1994

Signed by

Surveyor's Michigan License No.

ate July 21,

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975