

SURVEY & REMONUMENTATION

FEB 23 2001

APPROVED _____ CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

SECTION 7

8/24/00 *JS*

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Midland County Remonumentation

493

For Corners in
Midland
(County)

Located In: Corner Code#:

- | | | |
|---------------------------------------|----------------------------|-------|
| 1. Public Land Survey | T. <u>13N</u> R. <u>1W</u> | J-11 |
| | T. _____ R. _____ | _____ |
| | T. _____ R. _____ | _____ |
| 2. Public Controlling | S. _____ T. _____ R. _____ | _____ |
| in Section | S. _____ T. _____ R. _____ | _____ |
| 3. Miscellaneous | S. _____ T. _____ R. _____ | _____ |
| Property in Section | S. _____ T. _____ R. _____ | _____ |
| 4. Lot No. _____, Recorded Plat _____ | | |
| 5. Private Claims _____ | | |

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on July 6, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1852, Burt
40.08 - 1/4 Cor - 80.14 Sec Cor.
Lynn 10" S14 1/2°E, 20 LINKS
Beech 14" N14°W, 10 LINKS

1902, Gibbs
Post w/stone around - set new post
Meas. West 40.04
Meas. East 40.12

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found no evidence of corner. Road has been newly rebuilt and paved. Set corner on line between I-11 and K-11 at proportional measurement per C.S.R. notes, i.e. 2641.77' East of I-11 and 2647.05' West of K-11. Accepted this position as the proper method of re-establishment of the lost corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" pipe with brass cap stamped "Midland County Remon Corner, P.S. #27458" in Mon. Box
Witnesses:
N16°E, 48.32' - N & T in P.P.
S05°E, 33.55' - 3" dia. steel fence post
N60°W, 65.85' - Top Cen. West end 15" C.M.P.
N65°E, 50.15' - Top Cen. East end 15" C.M.P.
North, 4.0' - C.L. Asphalt Pvm't



Signed by Mark R. Robison
Surveyor's Michigan License No. 27458

Date 9-15-2000

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 197

REVISED MAY 14, 197
REVISED JAN., 198