

Land Corner Recordation Certificate
Attachment B to 2018 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is ONLY for corners filed under the 2018 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2018 State Survey and Remonumentation Grant Agreement

- Notes:
• No more than two Original Public Land Survey Corners can be recorded on this certificate
• If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
• If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland Co. Jasper Twp.

Corner Type Survey Township Corner Code
Original Public Land Survey Corner
• MCL 54.202(g)
• MCL 54.262(g)
Property Controlling Corner
• MCL 54.202(i)
• MCL 54.262(h)
Protracted Public Land Survey Corner
• MCL 54.202(k)
• MCL 54.262(i)

Table with 13 columns (A-M) and 13 rows (1-13). Cell (4, F) contains a circled 9. Cell (11, C) contains '13N' and cell (11, D) contains '2W'. Cell (11, M) contains 'F4'.

Part A: Corner(s) History

F4 – C ¼ corner Sec. 9, T13N, R2W
- 1902 – CSR p. 136 – F. T. Gibbs – Sec. 9. Survey
Set Black Oak Post. No timber near for bearing.
40.04 – East. 40.12 – West.

Professional Surveyor's License No.: 26454