

**Land Corner Recordation Certificate**  
**Attachment B to 2018 Annual Grant Agreement**  
Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2018 State Survey and Remonumentation Grant Agreement

**Filing Requirement:** MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2018 State Survey and Remonumentation Grant Agreement

**Notes:**

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County

Jasper Twp.

**Corner Type**

**Survey Township**

**Corner Code**

Original Public Land  
Survey Corner

- MCL 54.202(g)
- MCL 54.262(g)

T 13N R 2W  
T  
T  
T

G4

Property Controlling  
Corner

- MCL 54.202(i)
- MCL 54.262(h)

S T R  
S T R  
S T R  
S T R

Protracted Public Land Survey  
Corner

- MCL 54.202(k)
- MCL 54.262(i)

T R  
T R  
T R  
T R

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2	6			5		4		3		2		1		2
3														3
4	7			8		9	●	10		11		12		4
5														5
6	18			17		16		15		14		13		6
7														7
8	19			20		21		22		23		24		8
9														9
10	30			29		28		27		26		25		10
11														11
12	31			32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

**Part A: Corner(s) History**

**G4** – ¼ Corner common to Sec. 9 & 10, T13N, R2W –

- 1831 – GLO – C. W. Christmas – Set ¼ post

1) Hemlock 10" S65°E 8 L.

2) Pine 30" S47°W 9 L.

- 1852 – GLO Resurvey – A. Burt – Old ¼ corner

3) W. Pine 10" S64°W 25½ L.

4) Hemlock 14" N44°E 44 L.

- 1902 – CSR p. 136 – Sec. 9 survey – F. T. Gibbs – old corner post standing

5) Pine stump S58°E 55

- 1973 – LCRC # 1076 – G. J. Gray (PS # 17741) – Set ½" x 18" bar and cap at occupied corner and using Gibbs witness stump. Remains of fence lines run to East and West and also South of this corner.

6) 356° Az 8.57' set 60d nail in 18" Maple

7) 274° Az 12.76' set 60d nail in 6" Maple

8) 219° Az 10.82' set 60d nail in 4" Maple

9) 94° Az 6.03' set 60d nail in 4" Cherry

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

**G4** – ¼ corner common to Sec. 9 & 10, T13N, R2W –  
Found ½" x 18" long iron rebar with cap # 17741 on N. side of R. R. Tie post. Down woven wire fence remains E, W & S. Condition of witnesses as follows: #1, 3 & 4 are gone; #2 – Found stp. – measured S30°W 7.5'± to centerline remains; #5 – Found shell of 18"± WPS with spike set vertical in NW root – S58°E 36.42' to spike; #6, 7, 8 & 9 are OK. It appears that witness # 2 would place corner on S. side of RR Tie post. Since ½" CIR fits Gibbs witness #5 and witness #2 within reason, the ½" CIR is accepted as a careful and faithful perpetuation of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

**G4** – ¼ Corner common to Sec. 9 & 10, T13N, R2W –  
Replaced ½" x 18" CIR # 17741 with stamped 4" DNR Aluminum Cap on 1" x 36" long galvanized iron pipe.  
Set Blue Composite Post 1' North  
S58°E 36.42' to fd. spike in NW root of 18"± Pine stump (#5)  
S32°W 10.84' to fd. 60d nail in NW side 7" Red Maple (#8)  
West 12.84' to fd. 60d nail in S. side 9" Red Maple (#7)  
N13°W 8.56' to fd. 60d. nail in E. side 21" Red Maple (#6)  
N84°E 6.08' to fd. 60d nail in N. side 8" Cherry (#9)  
N5°W 24.45' to set Nail & Tag in W. side 7" Red Maple scribed 'XBT'

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
Sept. 12, 2017	N43°31'52.5737"	W84°32'54.5076"	NAD83(2011)	2010
2 Static GNSS Baselines from 2 local OPUS Base stations adjusted by least squares.				

I, Craig W. McVean, in a field survey on Sept. 14, 2017 certify under the requirements of the State Survey and Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the Corner Recordation Act, 1970 PA 74, MCL 54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuated or monumented as described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.

Craig W. McVean

Craig W. McVean

Professional Surveyor's License No.: 39088

Michigan Dept. of Natural Resources,  
8015 Mackinaw Trail, Cadillac, Michigan, 49601

12/11/2018

Date



I, Brian D. Ferguson, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on August 29, 2018 and is accepted for filing in the Midland County Remonumentation Program.

Brian D. Ferguson

Professional Surveyor's License No.: 26454

Date