

Land Corner Recordation Certificate
Attachment B to 2018 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2018 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2018 State Survey and Remonumentation Grant Agreement

- Notes:
- No more than two Original Public Land Survey Corners can be recorded on this certificate
 - If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
 - If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County Jasper Twp.

Corner Type	Survey Township	Corner Code
Original Public Land Survey Corner	T 13N R 2W	L5
• MCL 54.202(g)	T R	
• MCL 54.262(g)	T R	
Property Controlling Corner	S T R	
• MCL 54.202(i)	S T R	
• MCL 54.262(h)	S T R	
Protracted Public Land Survey Corner	T R	
• MCL 54.202(k)	T R	
• MCL 54.262(i)	T R	

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6			5		4		3		2		1		2
3														3
4	7			8		9		10		11		12		4
5														5
6	18			17		16		15		14		13		6
7														7
8	19			20		21		22		23		24		8
9														9
10	30			29		28		27		26		25		10
11														11
12	31			32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

- L5** – ¼ corner common to Sections 12 & 13, T13N, R2W –
- 1831 – GLO – C. W. Christmas – Set ¼ post
 - 1) Hemlock 16" N10°E 12 L.
 - 2) Hemlock 9" S01°E 14 L.
 - 1852 – GLO Resurvey – A. Burt – Set qr. sec. post – No old qr. corner or line found.
 - 3) Y. Birch 6" S10°W 3 L.
 - 4) Maple 18" N43½°E 62 L.
 - 1972 – LCRC # 165 – J. H. Granger (PS # 16041) – ½" iron pipe reestablished by single proportionate measurement and existing lines of occupation. 5) B. P. South 41.7'; 6) Fence post North 38.0';
 - 7) Iron lies 2' South of existing asphalt road centerline.

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

L5 – ¼ corner common to Sections 12 & 13, T13N, R2W – LCRC # 165 is in error. No road here. No conclusive GLO evidence was found. Dug small area at single proportional position but nothing found. Thus set stamped 4" DNR Aluminum cap on 1" x 4' long galvanized iron pipe by single proportion to 1852 GLO measurements as follows: N89°29'50"W 2695.24'-grid (N89°27'W 2703.03'-GLO) to 'K5' and S89°29'50"E 2696.55'-grid (S89°27'E 2704.35'-GLO) to 'M5'. Corner in willow swamp. N45°E 72' to centerline 2-track bearing S60°E. DNR monument accepted as a careful and faithful reestablishment of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

L5 – ¼ corner common to Sections 12 & 13, T13N, R2W -
 Stamped 4" DNR Aluminum cap on 1" x 4' long galvanized iron pipe. Add ring of stones.
 Set Blue Composite post 1' NW.
 N45°E 38.87' to set nail and tag (N & T) in SE side 6" Red Maple scribed 'XBT'
 S80°E 12.34' to set N & T in N side 3" W. Oak
 S43°W 41.40' to set N & T in NW side 5" W. Oak
 N13°W 18.25' to set N & T in W. side 3" W. Oak

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
08/20/2018	N43°31'27.2274"	W84°29'55.4725"	NAD83(2011)	2010.00

Monument set with RTK GNSS. Position verified by static GNSS baselines from 2 Local OPUS Base stations.

I, Craig W. McVean, in a field survey on Aug. 20, 2018, certify under the requirements of the State Survey and Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the Corner Recordation Act, 1970 PA 74, MCL 54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuated or monumented as described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.

Craig W. McVee

12/11/2018
Date

Professional Surveyor's License No.: 39088
Michigan Dept. of Natural Resources,
8015 Mackinaw Trail, Cadillac, Michigan, 49601



I, Brian D. Ferguson, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on August 29, 2018 and is accepted for filing in the Midland County Remonumentation Program.

Brian D. Ferguson

Date _____

Professional Surveyor's License No.: 26454