MIDLAND COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

		Filing Req	uirement of Act 74, M	/IICN. PA 1970
For Corners In: Midland (County)		Located In	Corner Code #	
Public Land Survey Property Controlling in Section Miscellaneous Property in Section	ss ss	T 15N R 1W T R T R T R T R T R	D11	Register of Deeds Stamp & File Number
4. Lot No: 5. Private Claims: I, Craig W. McVean, in a requirements of PA 74, Mi and 2 above were in conforthe current manual of suitnterior, Bureau of Land Micorner points mentioned in of the Michigan Board of established, re-established. NOTE: Not more than be recorded on this ce	ichigan PA of ormance with rvey instruct anagement of a lines 3, 4 ard of Land Sund, monument	on Aug. 15, 2012 do of 1970, the corner poir or regulations of the United Sta or by a decree of a Cou nd 5 above were in con veyors or by a Decre ed, recovered, found as	the mentioned in lines 1 therefore as required in ates Department of the rt of Law and/or that the aformance with the rules see of a Court of Law; sexpressed below:	A B C D E F G H I J K L M 2
A. Description of original D11 - 1852 - GLO - W 1) Tamarack 6" 2) Spruce 5" N5	V. Burt – Se S68°E 26 L	et ¼ post.	nd/or subsequent restor	ration:

- 1899 CSR- L. 1, P. 66 F. J. Gibbs, petition survey Section 32. Set Tamarack post for comer. N89°15'W 40.04 to 'C11' N89°15'E 39.76 to 'E11'. South 39.75 to 'D12'.
- 1990 Record Survey L. 4, p. 626 and notes from Ayres Assoc. Notes show 'E11' Fd. ¾" pipe, 'D11' Not Set Calc. position on line between 'E11' & 'C11', 2630.95' East, 2647.45' West; 'C11' Not set Calc. by DBL line and distance North from 'C12' through N 1/16 (#3).
- 1997 Recorded survey L. 5, P. 582 P. M. Ciosek shows corner
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- D11 1/4 comer common to sections 29 & 32, T15N, R1W No evidence Ayres or Ciosek position were ever monumented. Excavated 13'± N & S x 6'± wide area along N-S fence. Found 3" x 1.5' long wood stake post with point. Two-31/2" x 1.7' long wood post bottoms were found alongside this post point. N-S Newer barb wire fence is 0.4' West. From stake post point measured grid bearing and distances as follows: N89°36'39"E 2629.44' (2639.34' – GLO, 2624.16' – FJG) to 'E11'; N89°44'29"W 2647.30' (2639.34' – GLO, 2642.64' – FJG) to 'C11' and S0°18'15"W 1316.10' (1311.75' – FJG) to set 2" Alum. Cap at found ancient fence corner post bottoms at the CN 1/16 corner of Section 32; Thence S0°14'47"W 1315.70' (1311.75' – FJG) to 3/" iron pipe at 'D12'. Based on the post point agreement with Gibb's historical survey and existing occupation accepted the wood stake post point as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- D11 Replace 3" x 1.5' wood stake post point with stamped 4" DNR Aluminum Cap on 1" x 4' long galvanized iron pipe. Placed stake point at base of N. side of pipe and the 2 wood post bottoms at the SE & SW side of pipe at its base as memorials.

Set Blue Carsonite Post 1' SW S45°W 28.79' to set Nail & Tag in NW side 3" Red Maple scribed 'XBT' S80°W 67.45' to set Nail & Tag in N. side 8" Oak scribed 'XBT N21°E 83.95' to set Nail & Tag in W. side 7" Oak

S63°E 68.27' to set Nail & Tag in NE side 13" Oak

Surveyor's Michigan License/No.:

39088

MICHIG. CRAIG W MCVEAN PROFESSIONAL SURVEYOR No. 39088