

**SURVEY &
REMONUMENTATION**

**APPROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY**

APR 28 1995

COMMISSION

130

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MIDLAND <small>(County)</small>	Located In:	Corner Code --#
1. Public Land Survey	T 15N R 1W	F-11
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

8 NOV 94 9:22 A.M.

BEVERLY J THAYER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, PAUL B. LAPHAM, in a field survey on JULY, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K
2	6		5		4		3		2		
3											
4	7		8		9		10		11		
5											
6	18		17		16		15		14		
7											
8	19		20		21		22		23		
9											
10	30		29		28		27		26		
11											
12	31		32		33		34		35		
13											

A. Description of original monument and accessories and/or subsequent restoration:

F-11: 1/4 Corner common to Sections 28 & 33.
1852 - Austin Burt, Y. Pine 7" S 17°W, 9 lks Hemlock 6" N 17°W, 25 lks
10/03/14 - Gibbs, Set piece of Boiler Grate for Corner.
No Recorded Surveys

3-27-91 Jones, Unrecorded Survey & field notes from files of Ayres Associates.
1 1/4"x5" Iron Bar, raised with 3/4" pipe.
Wit.-(1)S40°E, 54.44', Nail in 12" Oak..
(2)N5°E, 40.82', Nail in 8" Poplar..
(3)N45°W, 57.67', Nail in 8" Maple
(4)West 2642.59', E-11
(5)East 2642.54', G-11

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-11: 1/4 Corner common to Sections 28 & 33.
Found Witnesses by Jones (Ayres Assoc.) dug Hole in asphalt pvm't.
Found 2 - Grader Blades, side by side, at 2 1/2 feet deep. (could have been mistaken for one 1 1/4"x5" iron bar). Could not remove.
Set Monument on Jones point over grader blades.
Checked distance to West (E-11) 2642.80'
Checked distance to East (G-11) 2642.67'
Checked angle to North - 179° 28' 54".

Accepted as best available evidence of the position of the original corner & replaced with Standard Monument.

Corner, F-11 was approved for remonumentation at a Peer Review Committee Meeting on 11-02, 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11: 1/4 Corner common to Sections 28 & 33.
Set 5/8" x 18" re-rod with brass cap stamped "Midland Co. Remon. Cor. PS 9433" in Mon. Box
S 40°E, 54.44' - Nail in 12" Oak (1)
N 5°E, 40.82' Nail in 8" Poplar (2)
N 45°W, 57.67' Nail in 8" Maple (3)
S 45°W, 75.80' Nail & Tag in 6" Oak



Signed by Paul B. Lapham
Surveyor's Michigan License No. 9433

Date 11-03-94