

MAR 9 2000

## SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A., 1970For corners in  
MONROE (58)  
(County)

Located In:

Corner Code #

FRENCHTOWN TWP.

T 6 S R 9 E

Miscellaneous 1

1. Public Land Survey
2. Property Controlling  
in Section
3. Miscellaneous  
Property in Sec.
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims 476 - west line intersecting with line common to Sections 26 & 27

S T R  
S T R  
S T R  
S T R

RECEIVED FOR RECORD  
99 SEP 30 AM 9:06  
REGISTER OF DEEDS  
MONROE COUNTY, MICH

## 1998 &amp; 1999 G.B. Warnke Private Remonumentation Corner

Register of Deeds Stamp &amp; File Number

I, George B. Warnke, Jr., in a field survey on December 10, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and / or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:  
1817 - GLO - Joseph Fletcher - set post 52.29 chains south of corner common to Sections 22, 23, 26 & 27 = 3451.14 feet and witnesses: White Oak 20" N46W 37 lks & White Oak 20" N55E 44lks  
May, 1971 - Case & Fleck survey shows point being 3476.38 feet south of section corner  
December, 1975 - A.J. Marino found iron rod  
1976, 1977, 1979 & 1987 - G.B. Warnke found 5/8 inch iron rod  
Nov., 1988 & Sept., 1990 - J.C. Andrus found railroad spike  
May, 1990 - G.B. Warnke found 5/8" iron rod  
June, 1991 - J.C. Andrus found iron pin

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
Intersection of west line of Private Claim 476 & line common to Sections 26 & 27 - angle in Mentel Road - not in pavement.  
January, 1996 - found 5/8" iron rod in existing monument box in grass area being 39.5 feet easterly of east edge of Mentel Road pavement. Distance from point at corner common to Sections 22, 23, 26 & 27 compares with distances measured by others.  
12/10/1998 - found 5/8" iron rod in existing monument box. Rod was quite resistant to be removed. Set plastic remonumentation cap on found 5/8" iron rod in existing monument box.

RATIFIED BY PEER GROUP, PA 345 OF 1990, MONROE COUNTY, MICHIGAN, DATE 8/18/1998, COUNTY REP. [Signature]  
and is accepted as the best available evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Set plastic remonumentation cap on found 5/8" iron rod in existing monument box & Witnesses:  
South 25° West 82.60 feet to found PK nail in east face of electric pole  
South 55° West 257.65 feet to top nut of hydrant - west side of Mentel Road  
North 10° West 195.72 feet to top nut of hydrant - west side of Mentel Road  
North 65° West 39.5 feet to east edge of asphalt pavement of Mentel Road  
South 30° West 49.9 feet to east post of arrow sign

Signed by [Signature]  
Surveyor's Michigan License No. 19474

Date August 16, 1999