

# REMONUMENTATION

APR 28 1995

## COMMISSION

RATIFIED BY PEER GROUP  
PA 345 OF 1990  
MONROE COUNTY, MICHIGAN

date: 11/8/1994

County Rep.: *[Signature]*  
For corners in

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD  
94 DEC 16 PM 3:27

*[Signature]*  
REGISTER OF DEEDS  
MONROE COUNTY, MICH

Register of Deeds Stamp & File Number

MONROE (County)

Located In: BEDFORD Corner Code: ##  
TWP.

1. Public Land Survey T 8 S R 7 E C-1  
T R  
T R  
T R  
T R

2. Property Controlling S T R  
in Section S T R

3. Miscellaneous S T R  
Property in Sec. S T R

4. Lot No. , Recorded Plat  
5. Private Claims

#### 1994 MONROE COUNTY REMONUMENTATION PROGRAM

Peer Group approved corner on 11/8/1994 per Act 345 of 1990.

I, G.B. WARNKE, JR., in a field survey on 11/30/1994, 19  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law, established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2							
3												
4	7	3	9	10	11							
5												
6	18	17	16	15	14							
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

C-1, T8S, R7E, Bedford Township, Monroe County - ID No. 58 Section Corner Common to Sections 5 and 6  
(Secor Road at Ranch Road - Asphalt over concrete pavement)  
1920, G.L.O. Surveyor Joseph Wampler, intersect N Boundary 222 links W. of post set post at intersection  
corner of Sections 5 and 6 and witnessed: W. Oak 8 (inch) S.88°E. 45 links & W. Oak 10 (inch) S.84°W.  
30 links. 1894, A.F. Winney performed section survey monument not described. 1929, road plans show found  
stone at station 0+00. 1946, O.A. Case surveyed Golden Meadows Plat, Liber 9, Page 8. 1953, A.J. Marino  
found stone 0.1 foot west of edge of pavement. 1961, A.J. Marino witnesses note P.I. 1973, G.B. Warnke  
notes found railroad spike, cut "+", this spike is used by surveyors to present.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-1 - 9/26/1994, found 3/8 inch rebar 4 inches deep, 3.40 feet west of railroad spike. Dug a 36 inch X  
36 inch hole, found a stone at 22 inches deep, 2.60 feet west of railroad spike and / or 0.8 feet east of  
3/8 inch rebar. Found no post under stone, set a old 1 inch X 36 inch iron pipe in place of stone.  
11/30/94, placed monument box and set brass remonumentation cap on 1 inch x 36 inch iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1 - Set 1 inch X 36 inch iron pipe with brass remonumentation cap inside monument box to replace stone  
and is accepted as the best available evidence of the position of the original corner and Witnesses:  
South 45° West 43.00 feet to found nail/shiner in northerly face of utility pole  
South 45° East 54.46 feet to found nail/shiner in northerly face of utility pole  
North 25.55 feet to northeast face of the east sign post  
East 2.59 feet to found railroad spike  
North 35° West 36.30 feet to found PK nail/shiner in northeast face of guy pole

Signed by *[Signature]*  
Surveyor's Michigan License No. 19474

Date 11/30/1994

