## SURVEY & REMONUMENTATION

DEC 07 1994

## RATIFIED BY PEER GROUP PA 345 OF 1990 MONROE COUNTY, MICHIGAN date: 11/14/1993

## COMMISSION

RECEIVED FOR RECORD

County Rep. For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 OCT 12 PM 2: 15

- H
11
lumber

5.	Lot No, Recorded Plat
uuı	B. WARNKE, JR. in a field survey on 9/2/1994 19 ereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned es 1 and 2 above were in conformance with regulations and rules therefore

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: E-12, T8S, R7E, 1/4 Corner Between Sections 32 & 33

(Douglas Road near Summerfield Road)

1802, G.L.O. Surveyor Joseph Wampler set 1/4 post between Sections 32 & 33. / 1971 & 1972 witness cards note spike. / G.B. Warnke, 1973, 76, 80 & 81, used railroad spike. / A.J. Marino, 1959, found railroad spike, in 1946 notes F.S., & in 1948 notes F.I. / Case & Fleck, 1954, found R.R. spike. / Monroe County Road Commission widened & improved Douglas Road & set monument box in place of R.R. spike. G.B. Warnke, 6-17-1991, set 5/8 inch x 40 inch iron rod in monument box based on old witnesses. / Gordon MacCammon recorded corner in L.C.R.C., Liber 3, Pages 187-188, iron pin found in monument box.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-12 - On 11/02/1993, found chisled "+" over 5/8 inch iron rod in monument box. 9/2/1994, set 1 inch x 36 inch iron pipe with brass remonumentation cap over iron rod. Witnessed as shown below.

-C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-12 - Set 1 inch x 36 inch iron pipe with brass remonumentation cap over over 5/8 inch iron rod in monument box and is accepted as the best available evidence of the position of the original corner and Witnesses:

North 40° East 40.57' set nail/shiner over outline of previous nail/shiner in southwest face of 18 inch Sycamore tree

South 25° East 65.58' found square head nail/shiner in north face of power pole South 80° East 86.17' northwest corner of foundation of house No. 7016

West 32.16' (32.11' LCRC) found square head nail/shiner in east face of telephone pole (32.44' naid/shiner in north face of telephone pole)

North 75° West /18/.68' southeast commer of foundation of house No. 7023

Bigned by \_

Burveyor's Michigan License No

Date <u>9/2/1994</u>

3 mi 354

19474

HIERO

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

OF MICHIGA GEORGE B. Warnke, jr. AND BURVEYOR NO. 19474 NSED LAND