

SEP 12 1995

MONTCALM COUNTY REMONUMENTATION PROGRAM

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Montcalm
(County)

Located In:

Corner Code #

1. Public Land Survey Sec 8 T 11 R 7 D-5, S 1/4
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED

10 AUG 95 3:31 P.M.

VIRGINIA L. KNEPPER

REGISTER OF DEEDS
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, William Tingley a field survey on November 12, 1994,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

April 1, 1839, Noah Brookfield, Deputy Surveyor, GLO Notes

Set Post

Beech 8" S71°W 19 links
Beech 10" N20°E 43 links

November 1869 from R.D. McNutt's Index Cards 11-7 (39)

New Bearing Tree: Pine 26" N29°E 43 links
Beech 11" N65°W 3 links

1884, from Field Book 11-7, Page 32, Quarter Post 8 and 17

Reestablished equidistant (38.86) and on straight line between Corner 7-8-17-18 and 8-9-16-17

New Bearing Tree: Pine Stump 24" N26E 43-1/2 links

Fire Clay Mon, Black Smith Cinders, Sods

Montcalm County Road Commission Files

Power Pole South 45.90 feet
East end of Culvert Southeast 23.85 feet
West end of Culvert Southwest 29.60 feet
East end of Culvert Northeast 24.90 feet
West end of Culvert Southwest 25.90 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found fence post with metal spike in center

Found fire clay mon

Found bolt & pipe embedded in concrete on Southside of fire clay mon

Found nail in power pole South 45.48 feet

ACCEPTED BY THE MONTCALM COUNTY SURVEY PEER
GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN
PUBLIC ACT 345 OF 1990 AT A MEETING HELD 19/4/1995

William G. Tingley
William Tingley, PS, Chairman

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Remonumentation Corner and Monument Box over fire clay monument

Nail power pole South 45.48 feet
Top Center of riser box S60°E 54.50 feet
Centerline Maple 35" S25°W 76.20 feet
Centerline Maple 28" S 60°W 107.40 feet

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by William G. Tingley Date 19/4/1994, 1994

Surveyor's Michigan License No. 30104

