

SURVEY &
REMONUMENTATION

FEB 09 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Muskegon</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>9N</u> R <u>14W</u>	<u>E-9</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling In Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

4. Lot No. , Recorded Plat
 5. Private Claims

I, Stephen V. Vallier, in a field survey on November, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1837 G.L.O. (John Mullett) set section post.
 N 89° W 17 Links 8" Hemlock
 N 31° E 17 Links 12" Hemlock
- 1888 Old county survey records, page 36, show a 1/2 mile 2642.5' (reset corner) to G-8.
- 1891 Old county survey records, Page 48, show a 1/2 mile 2633' stone monument, no witnesses (reset corner.)
- 1929 M.C.R.C. shows a found stone and 1/2 mile measure of 2642.0' to G-8.
 NW 55.90' 21" Ash
 NE 41.05' NE corner head well
 SE 40.68' SE corner head well

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/2" iron pipe in a monument box at the center of road intersection. Old fence and tree line to the west. No evidence of double corners based on the 1888 and 1891 county survey records. Accepted the position of the found 1 1/2" iron pipe due to historical usage and supportive documentation. Evidence of perpetuation as G.L.O. position un-supportive

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced the found 1 1/2" iron pipe with a 2 1/4"x30" cast-iron monument with a county surveyors cap in monument box.

- | | | | |
|---------|---------|------------|---------------------------------------|
| S 52° E | 73.02' | 10" Poplar | Set 20d nail in the southeast side |
| S 45° E | 59.54' | Power Pole | Found nail in the east side |
| S 38° W | 123.65' | 20" Maple | Set 20d nail in the south side |
| S 90° W | 48.13' | Power Pole | Found nail in the west side |
| N 54° W | 101.59' | 60" Willow | Set 20d nail in the northwest side |
| N 15° E | 277.04' | Power Pole | Found railroad spike on the east side |

Signed by Stephen V. Vallier
 Surveyor's Michigan License No. 28428

Date 12/14/99
 28428

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1976
 REVISED JAN., 1983
 REVISED OCT., 1995

1999 DEC 16 AM 11:02

Mark F. Fairchild

Muskegon County
 Register of Deeds
 Muskegon, Michigan

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	13		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

POSITION OF SAID
 RECORDED CORNER
 REVIEWED & RATIFIED 7/13/99
 BY MUSKEGON COUNTY
 PEER GROUP IN ACCORDANCE
 WITH P.A. 345, OF 1990



142 2660