

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N. R. 24 W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 29 and 30

CORNER MONUMENT 1" galvanized pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED 5/4/61

WITNESSES TO CORNER..... Tamarack 6" N 29 E 63 Links



Cedar 6" S 13 W 26.5 Links

Cedar 6" S 88 E 38 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Location of this corner was determined by compassing and pacing along the section line from the south. The stumps of the two original bearing trees were found. One showed one-half of the upper face, the rest of the face was destroyed when the tree was sawed down. The lower face had grown over almost completely. The stump was too decayed to show any scribe marks. The other stump had rotted almost to ground level except for a hard slab on the side opposite the face. The stumps fit in species, size, bearing, and distance of the original field notes. Digging in the muck at the proper location uncovered the pointed stub of an old post. The stub had been preserved in the water; the rest of the post had completely rotted away. Without any doubt this was the stub of the original post.

Corner was set by A. Metsa and W. Oliver.

SURVEYOR'S SEAL

SIGNED

A. Metsa  
REGISTERED LAND SURVEYOR

DATE

5/5/61