## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Surveyor.

record.

Marquette	_ Located In:	Corner Code #	
(County)			20 20 20 20 20 20 20 20 20 20 20 20 20 2
1. Public Land Survey	T 45N R 30W	G10 G11	w V
2. Property Controlling in Section	S T R S T R S T R		
3. Miscellaneous Property in Sec.	S T R S T R		* **
4. Lot No. , Red 5. Private Claims	corded Plat	N	Register of Deeds Stamp & File Number  A B C D E F G H I J K L M
above were in conformance with instructions of the United States a Court of Law and /or that the other rules of the Michigan Boar re-established, monumented, recov	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requi Department of the Interior, Bureau of I corner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	ired in the current manual of survey Land Management or by a decree of Id 5 above were in conformance with a of a Court of Law; established,	, 5 , 6 —18 —17 — 16 — 15 — 14 — 13 —
A. Description of original m	nonument and accessories and/or	subsequent restoration:	13
			ned by Wells Burt, Deputy

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G10) The original post and accessories were not recovered. Monumented corners were recovered at G13 (reestablished in 1968) and G9 (perpetuated original corner position). The observed distance between these two is 10436.59 feet (GLO record 10560 feet), 123.41' shorter than the original record. At 7902.64 (GLO=7920) north of G13, I found the remains of an old post, down and rotting, approx. 3 ft. east of an old and down N-S barbed wire fence (wire on ground and of various ages), with two trees, a Balsam and a Poplar, not of record, having overgrown upper and lower blazes facing it. The position of this post fits with a stream crossing 2230' south (GLO = 2211') and with the GLO record measurements to the north and south shorelines of Harris Lake, south of G11. I conclude that the majority of the discrepancy with the GLO record between Gl3 and G9 properly belongs in the section line north of this corner and I accept the position of the post as the best available evidence of the position of the original corner. Drove a monument into the old post hole.

Surveyor, midway and on the Section line between Section corners 40.00 chains north and south. Set Cedar post. Cedar 14" N73E 9 links, Y.Birch 14" N47W 96 links. Found no subsequent record. (G11) Section corner common to Sections 27-28-33-34. 1848 - Established by Wells Burt, Deputy

Set Cedar post. Hemlock 10" N31E 28 links, Cedar 16" S60W 10 links. Found no subsequent

(G11) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner by double proportionate measurement between monumented corners G13 5268.43' South (GLO 5280'), E11 5290.41' West (GLO 5280'), J11 7936.28' East (GLO 7920.66'), and G10 2634.21' North (GLO 2640'). From the position thus established, I found the north and south shorelines of Harris Lake fitting very well with the GLO record (north shore 106'M vs. 112' GLO; and south shore 671'M vs. 686' GLO), as well as the stream crossing noted in the record as 6.5 chs. north of G11.

C. Description of monument for corner and access	ories established to	perpetuate locating the position of the corner:
(G10) Set 1"IDx32" I.pipe with 4" alum in hole left by old post. Set measuring nail with MDNR tag in th	_	(G11) Set 1"IDx32" I.pipe with 4" a Set measuring nail with MDNR tag in
9" Maple N56E 8.05' mrkd "1/4S NBT"	e side of:	10" Maple N33E 21.4' mrkd "S27 N 12" W.Birch S28E 17.0' "S34 N
9" Maple S27E 45.9' do		16" R.Pine S04W 12.6' "S33 N 6" Maple in clump N65W 20.9' "S28 N
8" Maple in clump S19W 20.5' do Set sq'd Cedar post adjacent.		Set sq'd Cedar post adjacent. Bearings are magnetic.
Bearings are magnetic.	(e)	Searings are magnetic.

with 4" alum. MDNR cap. NR tag in the side of: kd "S27 NBT" "S34 NBT" "S33 NBT" 9' "S28 NBT" ent. OF #164

Signed by Surveyor's Michigan License No

Date

09/06/2012

33986 For the Michigan Department of Natural Resources, Forest Resources Division

16923

16924

FORM APPROVED BY MICHIGAN STATE BOARD OF

STEPHAN J SZYSZKOSKI

LAND

SURVEYOR